



Northern States Power Company

414 Nicollet Mall  
Minneapolis, Minnesota 55401  
Telephone (612) 330-5500

February 11, 1983

Mr. James G. Keppler  
Director, Region III  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

MONTICELLO NUCLEAR GENERATING PLANT  
DOCKET NO. 50-263 LICENSE NO. DPR-22

The following is submitted in response to IE Bulletin No. 82-04:

IE Bulletin No. 82-04 discussed deficiencies in Bunker Ramo Corporation electrical penetration assemblies. The deficiencies included improperly crimped lugs, improperly identified penetration cables, incorrect lug types, loose connections and cracked or missing insulation.

No Bunker Ramo electrical penetrations are installed at Monticello Nuclear Generating Plant. There are no plans to install Bunker Ramo electrical penetrations. No further action will be taken in regards to this Bulletin.

Approximately 12 man-hours were expended in response to this Bulletin.

Yours truly,

C.E. Larson  
Director, Nuclear Generation

CEL/ts

cc Mr. C.H. Brown  
Mr. G. Charnoff