

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 2 A B V S 1 2 0 0 - 0 0 0 0 0 0 - 0 0 0 3 4 1 1 1 1 4 5
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 37 CAT 38

CON'T
0 1 REPORT SOURCE L 6 0 5 0 0 0 3 3 4 7 0 1 0 2 8 3 3 0 1 2 5 8 3 9
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

0 2 On 1/2/83, during an operator tour, a fire barrier penetration
0 3 from the East Cable Vault ceiling to the Containment Purge Duct Room
0 4 floor was discovered unsealed. The Construction Department had previously
0 5 removed the permanent seal in this area for a Design Change Package
0 6 and installed temporary fire retardent batting. There were no safety
0 7 implication; since the penetration was resealed with batting within
0 8 one hour after discovery as per Technical Specification 3.7.15.
7 8 9 80

0 9 SYSTEM CODE A B 11 CAUSE CODE D 12 CAUSE SUBCODE Z 13 COMPONENT CODE Z Z Z Z Z Z 14 COMP. SUBCODE Z 15 VALVE SUBCODE Z 16
7 8 9 10 11 12 13 14 15 16 17
17 LER/RO REPORT NUMBER 8 3 21 22 EVENT YEAR 23 24 SEQUENTIAL REPORT NO. 0 0 1 25 26 OCCURRENCE CODE 27 28 0 3 29 REPORT TYPE L 30 31 REVISION NO. 0 32
ACTION TAKEN X 18 FUTURE ACTION G 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0 0 0 0 22 ATTACHMENT SUBMITTED Y 23 NPD-4 FORM SUB. N 24 PRIME COMP. SUPPLIER Z 25 COMPONENT MANUFACTURER Z 9 9 9 9 26
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

1 0 It is theorized that an area d/p between rooms displaced the seal since
1 1 loose batting was found atop a conduit box running immediately below
1 2 the penetration. To preclude future occurrences, a procedure being
1 3 written will require the taping of both ends of an affected penetration
1 4 and tracking on an open item list until a permanent seal is placed.
7 8 9 80

1 5 FACILITY STATUS E 28 % POWER 0 6 7 29 OTHER STATUS N/A 30 METHOD OF DISCOVERY B 31 DISCOVERY DESCRIPTION Operator Observation 32
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
1 6 ACTIVITY CONTENT RELEASED OF RELEASE Z 33 Z 34 AMOUNT OF ACTIVITY N/A 35 LOCATION OF RELEASE N/A 36
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
1 7 PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION N/A 39
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
1 8 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION N/A 41
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
1 9 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION N/A 43
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
2 0 PUBLICITY RELEASED DESCRIPTION N/A 45
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

8302180450 830202
PDR ADOCK 05000334
S PDR

Attachment To LER 83-001/03L
Beaver Valley Power Station
Duquesne Light Company
Docket No. 50-334

No further information is available or needed to satisfy the reporting requirement.