



83 FEB 22 AM 10:38

February 15, 1983  
L-83-78

Mr. James P. O'Reilly  
Regional Administrator, Region II  
U.S. Nuclear Regulatory Commission  
101 Marietta Street, Suite 3100  
Atlanta, GA 30303

Dear Mr. O'Reilly:

Re: St. Lucie Unit No. 2  
Docket No. 50-389, 50.55(e), 82-014  
Valves Will Not Respond to Command Signals

On June 30, 1982, Florida Power & Light Company (FPL) notified Region II Office of Inspection and Enforcement, in accordance with the requirements of 10 CFR 50.55(e) of a potential deficiency regarding the failure of reactor shutdown cooling bypass valves to respond to command signals. FPL is drafting the final report at this time and will submit it by February 25, 1983.

Very truly yours,

A handwritten signature in cursive script, reading "Robert E. Uhrig".

Robert E. Uhrig  
Vice President  
Advanced Systems & Technology

REU/PPC/njb

OFFICIAL COPY  
IE 27

8302280128 830215  
PDR ADCK 05000389  
S PDR