

# LICENSEE EVENT REPORT

CONTROL BLOCK: 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | T | N | S | N | P | 1 | 200-00000-00 | 341111 | 41111 | 5

CON'T

01 | REPORT SOURCE | L | 605000327 | 7012183 | 8021883 | 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 | With unit 1 in mode 1 (20% power) at 1508 CST on 01/21/83, one feedwater flow  
03 | channel was declared inoperable due to failing low. This required entry into action  
04 | statement 7 of LCO 3.3.1.1. There was no effect upon public health and safety.  
05 | Previous occurrences - none.  
06 |  
07 |  
08 |

09 | SYSTEM CODE | 11A | 11A | 12C | 14Z99999 | 15Z | 16Z

17 | LER/RO REPORT NUMBER | 83 | 112 | 13 | 1L | 10

18 | X | 19 | 1Z | 1Z | 1Z | 10000 | 1N | 1N | 1Z | 1Z999

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 | Investigation revealed that the sense lines to channel 1-FT-3-35A (high- and low-sides)  
11 | were crossed. The cause has been attributed to personnel error in that during recent  
12 | modifications to the sense lines, the lines were incorrectly installed. The high and  
13 | low sense lines were corrected and channel operation verified at 1200 CST on 01/21/83.  
14 | Personnel have been instructed to verify installation of sense lines prior to returning  
 equipment to service.

15 | E | 1020 | 1NA | 1B | Operator observation

16 | Z | 1Z | 1NA | 1NA

17 | 1000 | 1Z | 1NA

18 | 1000 | 1NA

19 | Z | 1NA

20 | N | 1NA

8302280200 830218  
 PDR ADOCK 05000327  
 S PDR

NRC USE ONLY

Name of Preparer: H. R. Rogers /M. R. Harding

Phone: (615) 751-0349