

CONTROL BLOCK: 1 6 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 M S G G S 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5

LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T

0 1 REPORT SOURCE L 6 0 5 0 0 0 4 1 6 7 0 1 2 5 8 3 8 0 2 2 4 8 3 9

60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

0 2 While conducting a seismic qualification vibration test on the Division 2 D/G, on

0 3 January 25, 1983, the tachometer went downscale while speed was being increased. The

0 4 diesel was then shutdown. This is being reported pursuant to T.S.6.9.1.13.b as

0 5 required by T.S. Surveillance Requirement 4.8.1.1.3. The event had no effect on the

0 6 health and safety of the public and did not constitute a threat to plant safety.

0 7

0 8

0 9

SYSTEM CODE 9 10 CAUSE CODE 11 CAUSE SUBCODE 12 COMPONENT CODE 13 COMP. SUBCODE 19 VALVE SUBCODE 20

0 9 E 11 E 12 E 13 I N S T R U 14 E 15 Z 16

17 LER/RO REPORT NUMBER 21 22 EVENT YEAR 23 24 SEQUENTIAL REPORT NO. 25 26 OCCURRENCE CODE 27 28 29 REPORT TYPE 30 31 REVISION NO. 32

0 9 8 3 0 3 8 0 3 L 0

ACTION TAKEN 33 FUTURE ACTION 34 EFFECT ON PLANT 35 SHUTDOWN METHOD 36 HOURS 37 38 ATTACHMENT SUBMITTED 39 40 NPRD-4 FORM SUB. 41 PRIME COMP. SUPPLIER 42 COMPONENT MANUFACTURER 43

0 9 C 18 Z 19 Z 20 0 0 0 0 N 23 N 24 N 25 D 2 8 3 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

1 0 The cause was failure of a solid state chip in the tachometer relay. This was

1 1 caused by a short produced by a voltage surge from the hook up of maintenance and

1 2 test equipment. The tachometer was replaced and the test was satisfactorily

1 3 performed. This was not a valid test based on position C.2.e.2 of Reg. Guide 1.108.

1 4 This is a final report.

1 5 FACILITY STATUS 28 29 % POWER 30 OTHER STATUS 31 METHOD OF DISCOVERY 32 DISCOVERY DESCRIPTION 33

1 5 G 28 0 0 0 29 NA C 31 Observed during special test

1 6 ACTIVITY CONTENT 33 34 RELEASED OF RELEASE 35 AMOUNT OF ACTIVITY 36 LOCATION OF RELEASE 37

1 6 Z 33 Z 34 NA NA

1 7 PERSONNEL EXPOSURES 37 38 NUMBER 39 TYPE 40 DESCRIPTION 41

1 7 0 0 0 37 Z 38 NA

1 8 PERSONNEL INJURIES 40 41 NUMBER 42 DESCRIPTION 43

1 8 0 0 0 40 NA

1 9 LOSS OF OR DAMAGE TO FACILITY 42 43 TYPE 44 DESCRIPTION 45

1 9 Z 42 NA

2 0 PUBLICITY 44 45 ISSUED 46 DESCRIPTION 47

2 0 N 44

8303010185 830224  
PDR ADOCK 05000416  
S PDR

NRC USE ONLY

NAME OF PREPARER Matthew V. Rohrer and Boyd Shingleton PHONE: