

CONTROL BLOCK:

						1
--	--	--	--	--	--	---

 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

[illegible]

LER NO. 83-08/1T
DOCKET NO. 50-317
LICENSE NO. DPR 53
EVENT DATE 02-05-83
REPORT DATE 02-18-83
ATTACHMENT

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (CONT'D)

The cause for this event was the failure of CEA 26's and 28's RSPTs on December 22, 1982 and February 5, 1983, respectively. To ascertain CEA 26's failure was RSPT related, two (2) independent tests were conducted. The RSPTs were replaced with spares from stock. In conjunction with these failures, suspect RSPTs (3) were also replaced at this time, as a preventive maintenance measure.

These failed RSPTs are being returned to the vendor for repair and analysis. An updated report will be submitted following the vendor's analysis.