

CONTROL BLOCK: 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

REPORT SOURCE: L 6 0 5 0 0 0 4 1 6 7 0 1 2 8 8 3 8 0 2 2 4 8 3 9

DOCKET NUMBER: 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

EVENT DATE: 74 75 76 77 78 79 80

REPORT DATE: 80 81 82 83 84 85 86 87 88 89 90

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

On January 28, 1983, fire door 1A215 alarmed on the supervision system and would not reset, yet was verified to be closed. Fire detectors on one side of the door were verified operable and an hourly fire watch was established in accordance with T.S.3.7.7 action a. This had no effect on the health and safety of the public and did not constitute a threat to plant safety. The event is reported pursuant to T.S.6.9.2.

SYSTEM CODE: A B 11

CAUSE CODE: X 12

CAUSE SUBCODE: Z 13

COMPONENT CODE: Z Z Z Z Z Z Z 14

COMP. SUBCODE: Z 15

VALVE SUBCODE: Z 16

EVENT YEAR: 8 3 21 22

SEQUENTIAL REPORT NO.: 0 2 7 23 24 25 26

OCCURRENCE CODE: 9 9 27 28 29

REPORT TYPE: X 30

REVISION NO.: 0 31 32

LER/RO REPORT NUMBER: 17

ACTION TAKEN: E 18

FUTURE ACTION: Z 19

EFFECT ON PLANT: Z 20

SHUTDOWN METHOD: Z 21

HOURS: 0 0 0 0 22

ATTACHMENT SUBMITTED: N 23

NPRD-4 FORM SUB.: N 24

PRIME COMP. SUPPLIER: Z 25

COMPONENT MANUFACTURER: Z 9 9 9 9 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

The alarm was due to a door position switch being out of adjustment. The duration of the LCO was in excess of 7 days, therefore, this report is being submitted as a Special Report pursuant to T.S.6.9.2. The switch was adjusted and the door was returned to service on February 1, 1983. The LCO was closed on February 4, 1983, at 1800 hours. This is a final report.

FACILITY STATUS: G 28

% POWER: 0 0 0 0 29

OTHER STATUS: NA 30

METHOD OF DISCOVERY: A 31

DISCOVERY DESCRIPTION: Alarmed Condition 32

ACTIVITY CONTENT: Z 33

RELEASED OF RELEASE: Z 34

AMOUNT OF ACTIVITY: NA 35

LOCATION OF RELEASE: NA 36

PERSONNEL EXPOSURES NUMBER: 0 0 0 0 37

TYPE: Z 38

DESCRIPTION: NA 39

PERSONNEL INJURIES NUMBER: 0 0 0 0 40

DESCRIPTION: NA 41

LOSS OF OR DAMAGE TO FACILITY TYPE: Z 42

DESCRIPTION: NA 43

PUBLICITY: N 44

ISSUED DESCRIPTION: NA 45

8303010349 830224
PDR ADOCK 05000416
S PDR

NRC USE ONLY

NAME OF PREPARER: Matthew V. Rohrer and Boyd Shingleton

PHONE: