

## LICENSEE EVENT REPORT

CONTROL BLOCK: 

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80
---	---	---	---	---	---	---	---	---	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----

 (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1
---	---

 N C B E P 2 (2) 0 0 - 0 0 0 0 0 - 0 0 (3) 4 1 1 1 1 (4) (5)  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80CON'T  

0	1
---	---

 REPORT SOURCE L (6) 0 5 0 - 0 3 2 4 (7) 0 1 1 9 8 3 (8) 0 2 1 8 8 3 (9)  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

## EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

(0 2) During plant operation, it was discovered that both doors of the Reactor Building 20' elevation personnel air lock were simultaneously opened. Both doors were immediately closed and access was restricted through the air lock until the problem was corrected. This event did not affect the health and safety of the public.

(0 3)

(0 4)

(0 5)

(0 6)

(0 7) Technical Specifications 3.6.5.1, 6.9.1.9b

(0 8)

(0 9)

0	9
---	---

 SYSTEM CODE S A (11) CAUSE CODE E (12) CAUSE SUBCODE X (13) COMPONENT CODE P E N E T R (14) COMP SUBCODE A (15) VALVE SUBCODE Z (16)  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

17
----

 LEH/RO REPORT NUMBER 8 3 (17) EVENT YEAR 8 3 (18) ACTION TAKEN E (18) FUTURE ACTION X (19) EFFECT ON PLANT Z (20) SHUTDOWN METHOD Z (21) HOURS 0 0 0 0 (22) ATTACHMENT SUBMITTED N (23) NPRD-4 FORM SUB. Y (24) PRIME COMP. SUPPLIER A (25) COMPONENT MANUFACTURER X 9 9 9 (26)  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

## CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

(1 0) Misalignment of the inner door, attributed to wear from normal use, prevented proper engagement of the door interlock system bolt whenever the door was closed. The door, manufactured by Sonic Bar, was adjusted for proper engagement of the interlock system bolt and was returned to service. No further action regarding this event is planned.

(1 1)

(1 2)

(1 3)

(1 4)

1	5
---	---

 FACILITY STATUS E (28) % POWER 0 8 0 (29) OTHER STATUS NA (30) METHOD OF DISCOVERY A (31) DISCOVERY DESCRIPTION Operational Event (32)  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

1	6
---	---

 ACTIVITY CONTENT Z (33) RELEASED OF RELEASE Z (34) AMOUNT OF ACTIVITY NA (35) LOCATION OF RELEASE NA (36)  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

1	7
---	---

 PERSONNEL EXPOSURES NUMBER 0 0 0 (37) TYPE Z (38) DESCRIPTION NA (39)  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

1	8
---	---

 PERSONNEL INJURIES NUMBER 0 0 0 (40) DESCRIPTION NA (41)  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

1	9
---	---

 LOSS OF OR DAMAGE TO FACILITY TYPE Z (42) DESCRIPTION NA (43)  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

2	0
---	---

 PUBLICITY ISSUED N (44) DESCRIPTION NA (45)  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 808303010400 830218  
PDR ADOCK 05000324  
S PDR

NRC USE ONLY

NAME OF PREPARER M. J. Pastva, Jr.

PHONE: 919-457-9521