

714/492-7700

ATTACHMENT TO LER 83-010
SOUTHERN CALIFORNIA EDISON COMPANY
SAN ONOFRE NUCLEAR GENERATING STATION
UNIT NO. 3, DOCKET NO. 50-362

SUPPLEMENTAL INFORMATION FOR CAUSE DESCRIPTION

It is believed that isolation of 3PI-8301 could have occurred during calibration of the detector and indicator performed on December 10, 1982, even though it successfully passed surveillance testing performed on January 3, 1983, prior to Mode 3 entry. During the January 3, 1983 surveillance, steam generator pressure was 90 psia and 3PI-8301 read 0, which is within the acceptance criterion of ± 120 psia.