

Mr. G. T. Perry FROM: J. H. Leonard DATE/TIME: December 15, 1978

Mr. Royce H. Grier
Director of Regulatory Operation
USNRC Region I
631 Park Avenue
King of Prussia, PA. 19406

12/18/78

SUBJECT: PROMPT REPORTABLE OCCURRENCE
DOCKET NO. 50-333 LICENSE NO. 01A-59
ASSIGNED GR NO. 75-151
LEB NO. 78-02701X 0

IDENT DATE: December 15, 1978

REPORT DATE: December 15, 1978

EVENT DESCRIPTION: During scheduled December performance of surveillance on the temperature switches associated with detection of HPCI Turbine/Steam line area high temperature, it was discovered that the instruments had been set above the limit specified by Technical Specification Table 3.2-2 during the November, 1978 surveillance. During November the switches were erroneously set approximately 75 above maximum ambient temperature instead of the specified $\leq 100^{\circ}$.

CLIENTS INVOLVED:
S-TS-94A, 23-TS-94B, 23-TS-117A, 23-TS-117B, 13-TS-101C, 13-TS-104D, 13-TS-107C and 13-TS-107D (Ambient Temperature Switches)
PRELIMINARY REMEDIAL ACTION:

Personnel used the wrong conversion table during the November surveillance. A correction will be placed in the surveillance procedure to clearly indicate the correct table. This should preclude recurrence.

ACTIVITY STATUS:

2 THERMAL 01 624

- | | |
|-----------------------|-------------------|
| a) Fueline Startup | g) Shutdown |
| b) Fueline Shutdown | h) Refueling |
| c) Steady State Power | i) Other |
| d) Load Change | j) Not Applicable |

Written follow-up report will be sent within two weeks.

TELECOPIED
TO: Mr. H. Grier
FROM: J. H. Leonard - JAL
DATE: 12-17-78
BY: J. H. Leonard

[Signature]
J. H. Leonard, Jr.
Assistant Director

781229 0246 5