

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 M I D C C 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5

LICENSEE CODE 14 LICENSE NUMBER 25 LICENSE TYPE 30 CAT 58

CON'T

0 1 REPORT SOURCE L 0 5 0 0 0 3 1 6 0 4 2 7 8 3 0 5 1 7 8 3 9

DOCKET NUMBER 58 EVENT DATE 74 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

0 2 DURING SURVEILLANCE TEST 12 THP 4030.STP.236, CHECK VALVE NS-262 (CCW SEAL WATER TO

0 3 THE H2 SAMPLING PUMPS) WAS FOUND TO BE LEAKING BY. THE H2 SAMPLING PUMPS WERE

0 4 TAGGED OUT UNDER A MAINTENANCE CLEARANCE TO REPAIR NS-262 AT 1309HRS ON 4-27-83.

0 5 THIS IS LESS CONSERVATIVE THAN T.S.3.6.4.1 REQUIRES. THE ACTION STATEMENTS WERE MET.

0 6 PUBLIC HEALTH AND SAFETY WERE NOT AFFECTED. NO PREVIOUS OCCURRENCES.

0 7

0 8

SYSTEM CODE S E 11 CAUSE CODE E 12 CAUSE SUBCODE B 13 COMPONENT CODE V A L V E X 14 COMP. SUBCODE C 15 VALVE SUBCODE A 16

LER/RO REPORT NUMBER 17 EVENT YEAR 8 3 SEQUENTIAL REPORT NO. 0 4 2 OCCURRENCE CODE 0 3 REPORT TYPE L REVISION NO. 0

ACTION TAKEN B 18 FUTURE ACTION Z 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0 0 0 22 ATTACHMENT SUBMITTED N 23 NPRO-4 FORM SUB. N 24 PRIME COMP. SUPPLIER A 25 COMPONENT MANUFACTURER R 3 4 4 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

1 0 CHECK VALVE NS-262 WAS DISASSEMBLED. THE CAUSE OF LEAKAGE WAS DUE TO DIRT BUILDUP

1 1 ON THE VALVE SEATING SURFACES. THE VALVE INTERNALS WERE CLEANED, THE SEATING SUR-

1 2 FACES CHECKED AND THE VALVE WAS REASSEMBLED. THE H2 SAMPLING PUMPS WERE RETURNED

1 3 TO SERVICE AT 1516HRS ON 4-27-83.

1 4

FACILITY STATUS E 28 % POWER 1 0 0 29 OTHER STATUS NA 30 METHOD OF DISCOVERY B 31 SURVEILLANCE TEST 32

ACTIVITY CONTENT RELEASED OF RELEASE Z 33 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36

PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION NA 39

PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION NA 41

LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43

PUBLICITY ISSUED IN 44 DESCRIPTION NA 45

8305240145 830517
PDR ADOCK 05000316
S PDR

NRC USE ONLY

NAME OF PREPARER D. ROBINSON PHONE: 616-465-5901

DMB



INDIANA & MICHIGAN ELECTRIC COMPANY

DONALD C. COOK NUCLEAR PLANT
P.O. Box 458, Bridgman, Michigan 49106
(616) 465-5901

May 17, 1983

Mr. J.G. Keppler, Regional Administrator
United States Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137


Operating License DPR-74
Docket No. 50-316

Dear Mr. Keppler:

Pursuant to the requirements of the Appendix A Technical Specifications,
the following report/s are submitted:

RO 83-042/03L-0

Sincerely,


W.G. Smith, Jr.
Plant Manager

/lab

cc: J.E. Dolan
R.S. Hunter
M.P. Alexich
R.F. Kroeger
B. Germano
E.R. Swanson/N.E. DuBry RO:III
R.C. Callen MPSC
G. Charnoff, Esq.
J.M. Hennigan
R.O. Bruggee EPRI
INPO
PNRRC
J.F. Stietzel
E.L. Townley
Dir., IE (30 copies)
Dir., MIPC (3 copies)

MAY 19 1983 IE22