

**Detroit
Edison**

Donald A. Welis
Manager-Quality Assurance
(313) 237-9657
2000 Second Avenue
Detroit, Michigan 48226
(313) 237-8000

April 15, 1982
EF2-57463

Mr. James G. Keppler, Regional Administrator
Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Subject: Interim Report of 10CFR50.55(e) Item on Stainless Steel Piping
(SA 312TP316 and TP316HF) (#62)


Dear Mr. Keppler:

On March 17, 1982, Project Quality Assurance's Mr. E.L. Thompson, Acting Supervisor-Construction Quality Assurance, telephoned Mr. P. Pelke of NRC-Region III, to report on a problem with Stainless Steel Piping (SA 312TP316 and TP316HF) at the Fermi 2 site.

In a number of locations SA 312TP316 and SA 312TP316H have been installed in lieu of the required SA 312TP316L. Deviation Disposition Requests have been written on piping where this problem exists. Investigation is being conducted to segregate any remaining materials that have not been installed. Edison Engineering is presently evaluating the acceptability of the installed piping. Reportability will be determined by the results of the engineering evaluation.

Another report on this item, either interim or final, is scheduled to be sent to you on or before August 13, 1982. If you have questions concerning this matter, please contact Mr. H.A. Walker, Supervisor-Construction Quality Assurance.

Very truly yours,



DAW/HAW/cp

cc: Mr. Richard DeYoung, Director
Office of Inspection and Enforcement
Division of Reactor Inspection Programs
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. Bruce Little, Resident Inspector
U.S. Nuclear Regulatory Commission
6450 North Dixie Highway
Newport, Michigan 48166



8204270255

S

APR 21 1982

IE27510