

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 FILSLS1 200-00000-00 341111 4 5
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

CON'T
01 L605000335706228230722829
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30
REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 Twice during normal full power operation, one of the 4 redundant 120 Volt
03 AC instrument power busses was lost when the output breaker of the 1A
04 static inverter opened. The second event occurred on 06-23-82 (29 hours
05 later). Each event caused the loss of one channel of the reactor
06 protection and engineered safeguards systems. In both cases the bus
07 was returned to service immediately by use of the associated maintenance
08 bypass bus. Public health and safety were not affected.
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

09 ED X Z GENERA F Z
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30
SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP SUBCODE VALVE SUBCODE

17 82 026 03 L 0
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30
LER/RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.

XZ Z Z 0000 N N Z G195
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30
ACTION TAKEN ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPROW FORM SUB PRIME COMP SUPPLIER COMPONENT MANUFACTURER

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 Upon investigation in each case, no apparent cause for the events was found.
11 The 1A inverter was found to be functioning properly. After the second
12 occurrence, the oscillator circuit board was replaced as a preventive
13 measure based upon a previous event of this type (ref LER 335-76-26). The
14 output breaker was reclosed and the line up returned to normal.
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

15 E9 9 NA Z NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30
FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION

15 ZZ NA NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30
ACTIVITY CONTENT RELEASED OR RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE

17 000 Z NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION

18 000 NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30
PERSONNEL INJURIES NUMBER DESCRIPTION

19 Z NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30
LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION

20 N NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30
PUBLICITY ISSUED DESCRIPTION

NAME OF PREPARER P.L. Pace PHONE (305) 552-3654