

UNIT SHUTDOWNS AND POWER REDUCTIONS

REPORT MONTH August 1982DOCKET NO. 50-266UNIT NAME Point Beach Unit '1DATE September 7, 1982COMPLETED BY C. W. FayTELEPHONE 414/277-2811

No.	Date	Type ¹	Duration (Hours)	Reason ²	Method of Shutting Down Reactor ³	Licensee Event Report No.	System Code ⁴	Component Code	Cause and Corrective Action To Prevent Recurrence
4	820815	S	0	B	4	N/A	HH	HTEXCH	Load reduced to complete condenser tube leak test. Five small leaks were detected and repaired in No. 2 waterbox.

¹ F: Forced
S: Scheduled

² Reason:
A- Equipment Failure (explain)
B- Maintenance or Test
C- Refueling
D- Regulatory Restriction
E- Operator Training & License Exam
F- Administrative
G- Operational Error (explain)
H- Other (explain)

³ Method:
1- Manual
2- Manual Scram
3- Automatic Scram
4- Other (explain)

⁴ Exhibit G-Instructions for Preparation of Data Entry Sheets for LER File (NUREG-0161)

⁵ Exhibit I- Same Source

UNIT SHUTDOWNS AND POWER REDUCTIONS

REPORT MONTH August 1982

DOCKET NO. 50-301

UNIT NAME Point Beach Unit 2DATE September 7, 1982COMPLETED BY C. W. FayTELEPHONE 414/277-2811

No.	Date	Type ¹	Duration (Hours)	Reason ²	Method of Shutting Down Reactor ³	Licensee Event Report No.	System Code ⁴	Component Code	Cause and Corrective Action To Prevent Recurrence
4	820828	S	33.6	A	1	N/A	CB	VALVE	Shutdown resulted from replacement of isolation valve 2-560A of reactor coolant system's RTD manifold from what is believed to be a plug stem separation.

¹ F: Forced
S: Scheduled

² Reason:
A- Equipment Failure (explain)
B- Maintenance or Test
C- Refueling
D- Regulatory Restriction
E- Operator Training & License Exam
F- Administrative
G- Operational Error (explain)
H- Other (explain)

³ Method:
1- Manual
2- Manual Scram
3- Automatic Scram
4- Other (explain)

⁴ Exhibit G-Instructions for Preparation of Data Entry Sheets for LER File (NUREG-0161)

⁵ Exhibit I- Same Source