

U.S. NUCLEAR REGULATORY COMMISSION
LICENSEE EVENT REPORT

CONTROL BLOCK / / / / / / (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
 /0/1/ /V/A/N/A/S/1/ (2) /0/0/-/0/0/0/0/0/-/0/0/ (3) /4/1/1/1/1/ (4) / / / (5)
 LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT
 /0/1/ REPORT /L/ (6) /0/5/0/0/0/3/3/8/ (7) /0/5/1/1/8/3/ (8) /0/6/0/1/8/3/ (9)
 SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

/0/2/ / On May 11, 1983, during Mode 1 operation, the containment personnel hatch inner /
 /0/3/ / door failed its leakage surveillance test. Since the outer door was still avai- /
 /0/4/ / lable to provide adequate containment integrity the health and safety of the /
 /0/5/ / public were not affected. This event is contrary to T.S. 3.6.1.3 and reportable /
 /0/6/ / pursuant to T.S. 6.9.1.9.b. /
 /0/7/ / /
 /0/8/ / /

SYSTEM CODE	CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE	COMP. SUBCODE	VALVE SUBCODE
/0/9/ /S/D/ (11)	/C/ (12)	/Z/ (13)	/P/E/N/E/T/R/ (14)	/A/ (15)	/Z/ (16)
LER/RO REPORT NUMBER	EVENT YEAR	SEQUENTIAL REPORT NO.	OCCURRENCE CODE	REPORT TYPE	REVISION NO.
(17) /8/3/	/-/	/0/3/0/	/ \ /	/0/3/	/L/
	/-/	/0/			

ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB.	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER
/B/ (18)	/Z/ (19)	/Z/ (20)	/Z/ (21)	/0/0/0/0/ (22)	/N/ (23)	/Y/ (24)	/A/ (25)	/C/3/1/0/ (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

/1/0/ / Containment entries had been made prior to conducting the surveillance. During /
 /1/1/ / this time the inner door seal became dirty to the point of not being capable of /
 /1/2/ / providing an adequate seal. The seal was cleaned, lubricated and retested /
 /1/3/ / satisfactorily. No further corrective action is required. /
 /1/4/ / /

FACILITY STATUS	%POWER	OTHER STATUS	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION (32)
/1/5/ /E/ (28)	/0/2/9/ (29)	/ NA / (30)	/B/ (31)	/ Surveillance Test /
ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY (35)	LOCATION OF RELEASE (36)	
/1/6/ /Z/ (33)	/Z/ (34)	/ NA /	/ NA /	
PERSONNEL EXPOSURES NUMBER	TYPE	DESCRIPTION (39)		
/1/7/ /0/0/0/ (37)	/Z/ (38)	/ NA /		
PERSONNEL INJURIES NUMBER	DESCRIPTION (41)			
/1/8/ /0/0/0/ (40)	/ NA /			
LOSS OF OR DAMAGE TO FACILITY TYPE	DESCRIPTION (43)			
/1/9/ /Z/ (42)	/ NA /			
PUBLICITY ISSUED	DESCRIPTION (45)			
/2/0/ /N/ (44)	/ NA /			

NRC USE ONLY
/ / / / / / / / / / /

NAME OF PREPARER E. Wayne Harrel PHONE (703) 894-5151

Vepco

VIRGINIA ELECTRIC AND POWER COMPANY

NORTH ANNA POWER STATION

P. O. BOX 402

MINERAL, VIRGINIA 23117

June 1, 1983

83 JUN 6 PG: 23
USNRO REGION 1
ATLANTA, GEORGIA

Mr. James P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Serial No. N-83-069
NO/CLF: nih
Docket No. 50-338
License No. NPF-4


Dear Mr. O'Reilly:

Pursuant to North Anna Power Station Technical Specifications, the Virginia Electric and Power Company hereby submits the following License Event Report for North Anna Unit No. 1.

Report No.	Applicable Technical Specifications
LER 83-030/03L-0	T.S. 6.9.1.9.b

This report has been reviewed by the Station Nuclear Safety and Operating Committee and will be forwarded to Safety Evaluation and Control for their review.

Very Truly Yours,


E. Wayne Harrell
Station Manager

for

Enclosures (3 copies)

cc: Document Control Desk (1 copy)
016 Phillips Bldg.
U.S. Nuclear Regulatory Commission
Washington, D. C. 20555

OFFICIAL COPY

IE 22
11