




**GULF STATES UTILITIES COMPANY**

POST OFFICE BOX 2951 • BEAUMONT, TEXAS 77704

AREA CODE 713 838-6631

May 31, 1983  
RBG - 15,164  
File Nos. G9.5, G9.25.1.1

Mr. John T. Collins, Regional Administrator  
U. S. Nuclear Regulatory Commission  
Region IV, Office of Inspection and Enforcement  
611 Ryan Plaza Drive, Suite 1000  
Arlington, TX 76011




Dear Mr. Collins:

River Bend Station Unit 1  
Docket No. 50-458  
Interim Report/DR-74

In our Interim Report dated March 28, 1983, Gulf States Utilities Company (GSU) informed Region IV of the status of the condition potentially reportable under 10CFR50.55(e) concerning the incorrect installation of  $\frac{1}{4}$ -inch drilled-in-expansion-type anchor bolts (DR-74). These anchor bolts are used to seismically support emergency lighting battery units in the River Bend Station control room.

GSU has requested additional information from our architect-engineer and we expect to receive this information by July 29, 1983. An interim or final status report will be provided by August 18, 1983.

Sincerely,

  
for J. E. Booker  
Manager-Engineering,  
Nuclear Fuels & Licensing  
River Bend Nuclear Group

<sup>PgQ</sup>  
JEB/PJD/do

cc: Director of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555

R. L. Brown (SRI)

8306090365 830531  
PDR ADOCK 05000458  
S PDR

IE-27 1/0