

DUKE POWER COMPANY

P.O. BOX 33189
CHARLOTTE, N.C. 28242

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION

TELEPHONE
(704) 373-4531

June 3, 1983

Mr. James P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street NW, Suite 2900
Atlanta, Georgia 30303

Re: McGuire Nuclear Station Unit 2
Docket No. 50-370

83 JUN 7 9:26
USNRC REGION II
ATLANTA, GEORGIA

Dear Mr. O'Reilly:

My letter of May 17, 1983 submitted Reportable Occurrence Report RO-370/83-07 which dealt with discrepancies in the Unit 2 Initial Integrated Leak Rate Test. In addition to the corrective actions outlined in the report, upon writing the periodic test procedure for the Unit 2 ILRT, the soap bubble test of the hot penetrations will be incorporated.

Very truly yours,

H.B. Tucker / HBU

Hal B. Tucker

PBN:jfw

cc: Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339

Mr. W. T. Orders
NRC Resident Inspector
McGuire Nuclear Station

8306130312 830603
PDR ADOCK 05000370
S PDR

OFFICIAL COPY
10-22-10