

Indian Point 3  
Nuclear Power Plant  
P.O. Box 215  
Buchanan, New York 10511  
914 739.8200



June 7, 1983  
IP-JAS-1583

Docket No. 50-286  
License No. DPR-64

James M. Allan, Acting Regional Administrator  
Region 1  
U. S. Nuclear Regulatory Commission  
631 Park Avenue  
King of Prussia, Pennsylvania 19406


Subject: I. E. Bulletin No. 83-03  
Check Valve Failures in Raw  
Water Cooling Systems Of  
Diesel Generators

Dear Mr. Allan:

The Indian Point 3 diesel generators are supplied with cooling water from the normally operating service water system water header. Using the piping boundary criteria from Action Item 1 of the subject bulletin, a review was conducted of the piping loops which branch off the normally operating service water header to the diesel generators and through to the discharge canal. It has been determined that there are no check valves located within the defined piping boundary.


Based on the above determination, there is no further action required to be taken by the Authority on the subject bulletin. Approximately 41 man hours were expended in investigation and preparation of this report.

Very truly yours,

  
John C. Brons  
Resident Manager

JCB:ms

SUBSCRIBED AND SWORN TO  
BEFORE ME THIS 7<sup>th</sup> DAY  
OF June, 1983.



RUTHANNE B. BOWMAN  
Notary Public, State of New York  
No. 4851904, Westchester County  
Commission Expires March 30, 1985

8306210068 830607  
PDR ADDCK 05000286  
Q PDR

TE 11  
1/2