

LICENSEE EVENT REPORT

CONTROL BLOCK: 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 M I D C C 1 2 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5

CON'T
01 L 6 0 5 0 0 0 3 1 5 7 0 5 1 5 8 3 8 0 6 0 8 8 3 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10
012 | WHILE PERFORMING A ROUTINE TOUR AN OPERATOR DISCOVERED THAT THE CHART PAPER ON THE
013 | CONTAINMENT SUMP FLOW MONITORING RECORDER (1-CS-001) WAS NOT ADVANCING. THIS EVENT
014 | WAS NON-CONSERVATIVE WITH RESPECT TO TECHNICAL SPECIFICATION 3.4.6.1.b. THE ACTION
015 | REQUIREMENTS WERE MET. PUBLIC HEALTH AND SAFETY WERE NOT AFFECTED. THIS IS THE
016 | FIRST OCCURRENCE OF THIS TYPE.

017 |
018 |

019 I E 11 E 12 E 13 I N I S I T I R U 14 R 15 Z 16
17 8 3 0 4 4 0 3 L 0
18 Z 19 Z 20 Z 21 0 0 0 0 N 23 Y 24 N 25 E 3 3 0 0

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27
110 | INVESTIGATION REVEALED THAT THE HOLES IN THE CHART PAPER THAT ARE USED TO ADVANCE
111 | THE PAPER BY MEANS OF THE PAPER DRIVE WHEEL HAD RIPPED. THE CHART PAPER WAS REALIGNED
112 | ON THE DRIVE WHEEL AND THE RECORDER WAS VERIFIED TO BE OPERATING CORRECTLY. NO
113 | FURTHER ACTION IS PLANNED.

114 |
115 E 28 1 0 0 29 NA 30 B 31 OPERATOR OBSERVATION 32
116 Z 33 Z 34 NA 35 NA 36
117 0 0 0 37 Z 38 NA 39
118 0 0 0 40 NA 41
119 Z 42 NA 43
120 N 44 NA 45

8306210273 830608
PDR ADOCK 05000315
S PDR