


INDIANA & MICHIGAN ELECTRIC COMPANY

DONALD C. COOK NUCLEAR PLANT
P.O. Box 458, Bridgman, Michigan 49106
(616) 465-5901

June 3, 1983

Mr. J.G. Keppler, Regional Director
Office of Inspection and Enforcement
United States Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

Operating License DPR-74
Docket No. 50-316

Dear Mr. Keppler:

This is to confirm my verbal report to your Mr. E.R. Swanson at 0845 hours on June 3, 1983. At this time I informed Mr. Swanson that upon exiting the Unit 2 upper containment through the airlock our Maintenance personnel discovered that a gauge had been removed from the outside wall of the outer airlock door thus providing a vent path from containment to the Aux Building when the inner airlock door is open for entry and egress.

The Maintenance men immediately notified the Operations Department of this problem and proceeded to reinstall the pressure gauge. Upon reinstallation the gauge fittings were checked for leaks utilizing the snoop technique which revealed no leaks.

As required by Technical Specification 6.9.1.12 a follow-up letter will be submitted within 14 days.

Sincerely,

E.L. Townley

E.L. Townley
Asst. Plant Manager

/jas

cc: J.E. Dolan
R.S. Hunter
M.P. Alexich
D. Wigginton, NRC
R.F. Kroeger
B. Germano
R.C. Callen MPSC
J.M. Hennigan
INPO

R.O. Bruggee EPRI
PNSRC
G. Charnoff, Esq.
E. Swanson/N. DuBry
J.F. Stietzel
W.G. Smith, Jr.
Dir., IE (40 copies)
Dir., MIPC (4 copies)

8306210325 830603
PDR ADDCK 05000316
S PDR

JUN 8 1983
IE22 1/0