

DUKE POWER COMPANY

P.O. BOX 33189
CHARLOTTE, N.C. 28242

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION

TELEPHONE
(704) 373-4531

March 23 1983 8 A 8: 57

Mr. James P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30303


Re: RII:RCD
McGuire Nuclear Station
Docket Nos. 50-369, 50-370
IE Bulletin 83-01

Dear Mr. O'Reilly:

This letter is in response to IE Bulletin 83-01 which concerned the failure of reactor trip breakers (Westinghouse DB-50) to open on automatic trip signal. A review of plant records has shown that no Westinghouse type DB-50 breakers are used at McGuire Nuclear Station in either safety related or non-safety related applications.

I declare under penalty of perjury that the statements set forth herein are true and correct to the best of my knowledge.

Very truly yours,



Hal B. Tucker

WHM/php

cc: Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. W. T. Orders
NRC Senior Resident Inspector
McGuire Nuclear Station

8303210268 830302
PDR ADOCK 05000369
Q PDR

IE31