

LICENSEE EVENT REPORT

CONTROL BLOCK:

1	2	3	4	5	6
---	---	---	---	---	---

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	G	A	E	I	H	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4	5
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

7 8 9 14 15 25 26 30 57 CAT 58

CON'T

0	1	L	6	0	5	0	0	0	3	6	6	7	0	2	1	2	8	3	8	0	3	0	8	8	3	9
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During completion of the "RCIC PUMP OPERABILITY" procedure, the RCIC
03 trip and throttle valve failed to manually trip. RCIC was declared in-
04 operable as per Action 26 for Item 5 of Tech. Specs. Table 3.3.2-1. The
05 plant was placed into a 14-day LCO as per Tech. Specs. 3.7.3, ACTION a
06 (the HPCI system remained operable). The health and safety of the public
07 were not affected by this non-repetitive event.

0	8
---	---

7 8 9 80

0	9	C	E	11	E	12	B	13	I	N	S	T	R	U	14	S	15	Z	16
---	---	---	---	----	---	----	---	----	---	---	---	---	---	---	----	---	----	---	----

7 8 9 10 11 12 13 18 19 20

17	8	3	—	0	0	9	—	0	3	L	—	0
----	---	---	---	---	---	---	---	---	---	---	---	---

21 22 23 24 26 27 28 29 30 31 32

A	18	Z	19	Z	20	Z	21	0	0	0	0	N	23	N	24	N	25	L	2	0	0	26
---	----	---	----	---	----	---	----	---	---	---	---	---	----	---	----	---	----	---	---	---	---	----

33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The cause of this event was attributed to component failure. A torque
11 switch in the Limitorque valve operator was found failed. The torque
12 switch was replaced. The RCIC trip and throttle valve was then reset.
13 The RCIC system (including the trip and throttle valve) was then proven
14 operable per procedure and returned to service on 2/12/83.

1	5	E	28	0	6	9	29	NA	30	A	31	Operator Observation	32
---	---	---	----	---	---	---	----	----	----	---	----	----------------------	----

7 8 9 10 12 13 44 45 46 80

1	6	Z	33	Z	34	NA	35	NA	36
---	---	---	----	---	----	----	----	----	----

7 8 9 10 11 44 45 80

1	7	0	0	0	37	Z	38	NA	39
---	---	---	---	---	----	---	----	----	----

7 8 9 11 12 13 80

1	8	0	0	0	40	NA	41
---	---	---	---	---	----	----	----

7 8 9 11 12 80

1	9	Z	42	NA	43
---	---	---	----	----	----

7 8 9 10 80

2	0	N	44	NA	45
---	---	---	----	----	----

7 8 9 10 80

8303210413 830308
PDR ADDCK 050003₆₆
S PDR

NAME OF PREPARER S. B. Tipps PHONE (912) 367-7851

NRC USE ONLY