



**LOUISIANA  
POWER & LIGHT**


142 DELARONDE STREET  
P O BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

March 7, 1983

L. V. MAURIN  
Vice President Nuclear Operations

W3I83-0071  
Q-3-A35.07.33

Mr. John T. Collins, Regional Administrator  
U. S. Nuclear Regulatory Commission  
Region IV  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76012



SUBJECT: Waterford SES Unit No. 3  
Docket No. 50-382  
Significant Construction Deficiency No. 33  
"Chilled Water Piping Supports"

REFERENCE: LP&L letter W3I82-0058 dated October 1, 1982

Dear Mr. Collins:

Two hangers remain to be reworked in the Chilled Water System to complete the corrective action. However, these hangers cannot be reworked at this time because they are in a controlled access area due to pre-operational testing. A final report will therefore be delayed until May 10, 1983.

If you have any questions, please advise.

Very truly yours,

*L. V. Maurin*  
L. V. Maurin

LVM/MAL:keh

cc: 1) Director  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

3) E. L. Blake

2) Director  
Office of Management  
Information and Program Control  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

4) W. M. Stevenson

8303210556 830307  
PDR ADDCK 05000382  
S PDR

IF 27