

GULF STATES UTILITIES COMPANY

POST OFFICE BOX 2951 • BEAUMONT, TEXAS 77704

AREA CODE 713 838-6631




June 16, 1983

RBG- 15,267

File Nos. G9.5, G9.25.1.1

Mr. John T. Collins, Regional Administrator
U. S. Nuclear Regulatory Commission
Region IV, Office of Inspection and Enforcement
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011




Dear Mr. Collins:

River Bend Station Unit 1
Docket No. 50-458
Interim Report/DR-119

On May 17, 1983, Gulf States Utilities Company (GSU) notified Region IV of a condition potentially reportable under 10CFR50.55(e) concerning the failure of threaded weld studs during the construction of cable tray supports (DR-119). GSU has not completed its investigation. An interim or final status report will be provided by August 2, 1983.

Sincerely,


for J. E. Booker
Manager-Engineering,
Nuclear Fuels & Licensing
River Bend Nuclear Group

^{PJD}
JEB/PJD/kt

cc: Director of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

R. L. Brown (SRI)

8306270130 830616
PDR ADOCK 05000458
S PDR

IE-27

1/0