


LICENSEE EVENT REPORT

CONTROL BLOCK: 

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 8 9 M I D C C 1 14 2 15 0 0 0 0 0 0 0 0 0 0 0 0 25 3 4 1 1 1 1 1 4 57 58  
 LICENSEE CODE LICENSE NUMBER LICENSE TYPE JO CAT 58  
 CON'T

CON'T

REPORT SOURCE: 01 8  
DOCKET NUMBER: 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80  
EVENT DATE: 051883  
REPORT DATE: 061683  
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES: 10

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | WHILE ON ROUTINE PLANT TOUR, A SECURITY GUARD DISCOVERED CD DIESEL ROOM CARDOX SYSTEM  
0 3 | ISOLATED WITH NO NAMES ON ENTRY BOARD AND NO PERSONNEL IN THE ROOM. THIS EVENT WAS  
0 4 | NON-CONSERVATIVE WITH RESPECT TO TECHNICAL SPECIFICATION 3.7.9.3. THE CONDITION  
1 5 | EXISTED FOR APPROXIMATELY 32 MINUTES. THE FIRE DETECTION SYSTEM WAS OPERABLE. PUBLIC  
HEALTH AND SAFETY WERE NOT AFFECTED. PREVIOUS OCCURRENCES OF A SIMILAR NATURE  
0 7 | INCLUDE: 315/82-037, 044, 045, 068, 081 AND 316/82-054, 076, 83-022, 028, 034.

SYSTEM CODE A B 11		CAUSE CODE A 12		CAUSE SUBCODE C 13		COMPONENT CODE I N S I T R I U 14		COMP SUBCODE S 15		VALVE SUBCODE Z 16	
LER-RO REPORT NUMBER 8 17		EVENT YEAR 8 3 21 22		SEQUENTIAL REPORT NO. 0 4 8 23 24 25 26		OCCURRENCE CODE 0 3 27 28 29		REPORT TYPE L 30		REVISION NO. 0 31 32	
ACTION TAKEN H 18		FUTURE ACTION Z 19		EFFECT ON PLANT Z 20		SHUTDOWN METHOD Z 21		HOURS 0 0 0 0 0 22 37 38 39 40		ATTACHMENT SUBMITTED N 23 41	
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)		NPR-4 FORM SUB. N 24 42		PRIME COMP. SUPPLIER N 25 43		COMPONENT MANUFACTURER C 1 2 5 26 44 45 46 47					

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

THE TECHNICIAN INVOLVED HAD ERASED HIS NAME FROM THE ENTRY BOARD BUT FAILED TO RETURN THE CARDOX SWITCH TO NORMAL. THE TECHNICIAN'S SUPERVISOR DISCUSSED THIS INCIDENT AND THE NEED FOR FULL COMPLIANCE WITH FIRE PROTECTION REQUIREMENTS WAS EMPHASIZED. IN ADDITION, THE SECURITY GUARD ASSIGNED AS SWITCH WATCH FAILED TO VERIFY THAT THE SWITCH WAS CORRECTLY POSITIONED. APPROPRIATE ADMINISTRATIVE ACTION WAS TAKEN.

SWITCH WAS CORRECTLY POSITIONED. APPROPRIATE ADMINISTRATIVE ACTION WAS TAKEN.

FACILITY STATUS (5) [E] (28) 11010 (29) OTHER STATUS (30) NA METHOD OF DISCOVERY (31) [B] (32) DISCOVERY DESCRIPTION SECURITY GUARD OBSERVATION  
 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (25)

SECURITY GUARD OBSERVATION

6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

PERSONNEL EXPOSURE

AMOUNT OF ACTIVITY (35) NA

LOCATION OF RELEASE (36) NA

NA

PERSONNEL EXPOSURES				
NUMBER	TYPE	DESCRIPTION		
7	000	37 Z 38	NA	80

NA

PERSONNEL INJURIES	NUMBER	DESCRIPTION
	41	

NA

0000 (40) NA  
a 9 11 12  
LOSS OF OR DAMAGE TO FACILITY (43)  
TYPE: RECORDS  
8306270436 830616  
PDR APOCK 05000315  
80

NA

TYPE		DESCRIPTION		NA		S		PDR	
7	Z	42							

PUBLICITY  
 ISSUED DESCRIPTION (45)  
 (N) (44) NA  
 NRC USE ONLY

NA

NRC USE ONLY

NAME OF PREPARER R. A. PALMER (616) 465-5901

NAME OF PREPARER R. A. PALMER

PHONE (616) 465-5901

017-920