

APPROVED BY OMB
3150-0011
EXPIRES 4-30-82

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

| | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
|---|---|---------------|---|---|---|---|---|----|----|----------------|---|---|---|---|---|----|--------------|---|---|---|----|--------|---|---|---|---|--|--|---|
| 0 | 1 | S | C | V | C | S | 1 | 2 | d | 0 | - | d | 0 | 0 | d | 0 | + | d | 0 | 3 | 4 | 1 | d | 0 | 0 | 4 | | | 5 |
| 7 | 8 | LICENSEE CODE | | | | | | 14 | 15 | LICENSE NUMBER | | | | | | 25 | LICENSE TYPE | | | | 30 | CAT 56 | | | | | | | |

CON'T

| | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
|---|---|---------------|----|----|---------------|---|---|---|---|---|---|---|----|------------|---|---|---|---|---|---|---|----|-------------|---|---|---|---|--|--|--|----|
| 0 | 1 | REPORT SOURCE | L | 6 | 0 | 5 | 9 | 0 | 0 | 3 | 9 | 5 | 7 | 0 | 1 | 2 | 7 | 8 | 3 | 8 | 0 | 3 | 1 | 7 | 8 | 3 | 9 | | | | |
| 7 | 8 | | 60 | 61 | DOCKET NUMBER | | | | | | | | 68 | EVENT DATE | | | | | | | | 74 | REPORT DATE | | | | | | | | 80 |

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | On January 27, 1983, with the Plant in Mode 1, the Main Control Board indication
0 3 | (PI-486) for Steam Generator "B" Steam Pressure decreased approximately 100 psig.
0 4 | The "Steam Line Hi DP" alarm was also received at the time of the observed
0 5 | discrepancy in pressure indication. There were no adverse consequences as SCE&G
0 6 | complied with the Action Statements of the applicable Technical Specifications.
0 7 |
0 8 |

| | | | | | | |
|----|----|----|----|----|----|----|
| 03 | 11 | 12 | 13 | 14 | 15 | 16 |
| 7 | 9 | 10 | 11 | 12 | 13 | 14 |
| 17 | 18 | 19 | 20 | 21 | 22 | 23 |
| 24 | 25 | 26 | 27 | 28 | 29 | 30 |
| 31 | 32 | 33 | 34 | 35 | 36 | 37 |
| 38 | 39 | 40 | 41 | 42 | 43 | 44 |

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The event is attributed to a plugged transmitter sensing line. The inoperable

1 1 channel was placed in the tripped condition within one (1) hour. Pressure

1 2 transmitter PT-486 was found to have a plugged sensing line. The sensing line

1 3 was back flushed and indication returned to normal. The licensee plans no

1 4 additional action in regards to this event.

| FACILITY STATUS | | % POWER | OTHER STATUS (30) | METHOD OF DISCOVERY | DISCOVERY DESCRIPTION (32) |
|-----------------|---|---------|-------------------|---------------------|-----------------------------|
| 1 | 5 | B (28) | 050 (29) | N/A | A (31) Operator Observation |

ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)

1 6 7 (33) 8 (34) N/A N/A

| PERSONNEL EXPOSURES | | | |
|---------------------|------|-------------|------|
| NUMBER | TYPE | DESCRIPTION | (39) |
| 1 7 | (37) | (38) | N/A |

| PERSONNEL INJURIES | | DESCRIPTION | | (41) |
|--------------------|---|-------------|-----|------------------------------------|
| 1 | 8 | (40) | | |
| | | | N/A | 8303240600 830317 back 05000395 |

| 1 | | 2 | | 3 | | 4 | | 5 | | 6 | | 7 | | 8 | | 9 | | 10 | | 11 | | 12 | |
|---|--|---|--|---|--|---|--|---|--|---|--|---|--|---|--|---|--|----|--|----|--|----|--|
| 1 | | 2 | | 3 | | 4 | | 5 | | 6 | | 7 | | 8 | | 9 | | 10 | | 11 | | 12 | |
| 1 | | 2 | | 3 | | 4 | | 5 | | 6 | | 7 | | 8 | | 9 | | 10 | | 11 | | 12 | |
| 1 | | 2 | | 3 | | 4 | | 5 | | 6 | | 7 | | 8 | | 9 | | 10 | | 11 | | 12 | |
| 1 | | 2 | | 3 | | 4 | | 5 | | 6 | | 7 | | 8 | | 9 | | 10 | | 11 | | 12 | |
| 1 | | 2 | | 3 | | 4 | | 5 | | 6 | | 7 | | 8 | | 9 | | 10 | | 11 | | 12 | |
| 1 | | 2 | | 3 | | 4 | | 5 | | 6 | | 7 | | 8 | | 9 | | 10 | | 11 | | 12 | |
| 1 | | 2 | | 3 | | 4 | | 5 | | 6 | | 7 | | 8 | | 9 | | 10 | | 11 | | 12 | |
| 1 | | 2 | | 3 | | 4 | | 5 | | 6 | | 7 | | 8 | | 9 | | 10 | | 11 | | 12 | |
| 1 | | 2 | | 3 | | 4 | | 5 | | 6 | | 7 | | 8 | | 9 | | 10 | | 11 | | 12 | |
| 1 | | 2 | | 3 | | 4 | | 5 | | 6 | | 7 | | 8 | | 9 | | 10 | | 11 | | 12 | |
| 1 | | 2 | | 3 | | 4 | | 5 | | 6 | | 7 | | 8 | | 9 | | 10 | | 11 | | 12 | |
| 1 | | 2 | | 3 | | 4 | | 5 | | 6 | | 7 | | 8 | | 9 | | 10 | | 11 | | 12 | |
| 1 | | 2 | | 3 | | 4 | | 5 | | 6 | | 7 | | 8 | | 9 | | 10 | | 11 | | 12 | |
| 1 | | 2 | | 3 | | 4 | | 5 | | 6 | | 7 | | 8 | | 9 | | 10 | | 11 | | 12 | |
| 1 | | 2 | | 3 | | 4 | | 5 | | 6 | | 7 | | 8 | | 9 | | 10 | | 11 | | 12 | |
| 1 | | 2 | | 3 | | 4 | | 5 | | 6 | | 7 | | 8 | | 9 | | 10 | | 11 | | 12 | |
| 1 | | 2 | | 3 | | 4 | | 5 | | 6 | | 7 | | 8 | | 9 | | 10 | | 11 | | 12 | |
| 1 | | 2 | | 3 | | 4 | | 5 | | 6 | | 7 | | 8 | | 9 | | 10 | | 11 | | 12 | |
| 1 | | 2 | | 3 | | 4 | | 5 | | 6 | | 7 | | 8 | | 9 | | 10 | | 11 | | 12 | |
| 1 | | 2 | | 3 | | 4 | | 5 | | 6 | | 7 | | 8 | | 9 | | 10 | | 11 | | 12 | |
| 1 | | 2 | | 3 | | 4 | | 5 | | 6 | | 7 | | 8 | | 9 | | 10 | | 11 | | 12 | |
| 1 | | 2 | | 3 | | 4 | | 5 | | 6 | | 7 | | 8 | | 9 | | 10 | | 11 | | 12 | |
| 1 | | 2 | | 3 | | 4 | | 5 | | 6 | | 7 | | 8 | | 9 | | 10 | | 11 | | 12 | |
| 1 | | 2 | | 3 | | 4 | | 5 | | 6 | | 7 | | 8 | | 9 | | 10 | | 11 | | 12 | |
| 1 | | 2 | | 3 | | 4 | | 5 | | 6 | | 7 | | 8 | | 9 | | 10 | | 11 | | 12 | |
| 1 | | 2 | | 3 | | 4 | | 5 | | 6 | | 7 | | 8 | | 9 | | 10 | | 11 | | 12 | |
| 1 | | 2 | | 3 | | 4 | | 5 | | 6 | | 7 | | 8 | | 9 | | 10 | | 11 | | 12 | |
| 1 | | 2 | | 3 | | 4 | | 5 | | 6 | | 7 | | 8 | | 9 | | 10 | | 11 | | 12 | |
| 1 | | 2 | | 3 | | 4 | | 5 | | 6 | | 7 | | 8 | | 9 | | 10 | | 11 | | 12 | |
| 1 | | 2 | | 3 | | 4 | | 5 | | 6 | | 7 | | 8 | | 9 | | 10 | | 11 | | 12 | |
| 1 | | 2 | | 3 | | 4 | | 5 | | | | | | | | | | | | | | | |

| PUBLICATION | | ISSUED | | DESCRIPTION | | NRC USE ONLY | |
|-------------|---|--------|--|-------------|--|--------------|--|
| 2 | 0 | 44 | | N/A | | | |

NAME OF PREPARER

PHONE: (803) 345-5209