



Pennsylvania Power & Light Company

Two North Ninth Street • Allentown, PA 18101 • 215/770-5151

May 16, 1983

Mr. J.M. Allan
Acting Regional Administrator, Region I
U.S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406

SUSQUEHANNA STEAM ELECTRIC STATION
LICENSEE EVENT REPORT ~~83-068/OIP-0~~ 83-075/OIP-0*
ER 100450 FILE 341-23
PLA-1670

Docket No. 50-387
License No. NPF-14

Dear Mr. Allan:

This transmission confirms the telephone report of May 15, 1983, by F.T. Eisenhuth to G.G. Rhoads of your staff, regarding interactions of the chlorine detector in the Control Room Emergency Outside Air Supply System (CREOASS) following a loss of power. Procedure changes have been instituted to provide operators with appropriate actions to ensure proper response of CREOASS. Any further corrective actions deemed necessary will be discussed in subsequent reports.

This condition is considered reportable in accordance with Technical Specification 6.9.1.8.1.

H.W. Keiser
Superintendent of Plant-Susquehanna

APP/pjg

cc: Director, Office Of Inspection & Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Director, Office of Management & Program Control
U.S. Nuclear Regulatory Commission
Washington, DC 20555

* REFERENCE PLA-1691 DATED MAY 27, 1983.

8307010069 830516
PDR ADOCK 05000387
S PDR

IE29.10