



REGION II
ATLANTA, GEORGIA

83 MAR 24 AM 1:10

**Florida
Power**
CORPORATION

March 22, 1983
312-0383-25

Mr. James P. O'Reilly
Regional Administrator, Region II
U.S. Nuclear Regulatory Commission
Office of Inspection & Enforcement
101 Marietta Street N.W., Suite 2900
Atlanta, GA 30303

Subject: Crystal River Unit 3
Docket No. 50-302
Operating License No. DPR-72
Licensee Event Report No. 83-005, Rev. 1

Dear Mr. O'Reilly:

Enclosed please find Licensee Event Report No. 83-005, Rev. 1 and the attached supplementary information sheet, which are submitted in accordance with Technical Specification 6.9.1.9.b.

This report deletes references indicating that the 175' wind speed instrumentation was out of calibration on February 1, 1983. This error was due to a misinterpretation of the Shift Supervisor's log. The instrumentation was temporarily taken out of service on February 1, 1983, to perform a surveillance procedure.

Sincerely,

G. R. Westafer
Manager,
Nuclear Licensing and Fuel Management

DP/caw

Enclosure

cc: Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

8304010597 830322
PDR ADOCK 05000302
S PDR

General Office 3201 Thirty-fourth Street South • P.O. Box 14042, St. Petersburg, Florida 33733 • 813-866-5151

OFFICIAL COPY

IE 22