



July 20, 1976
L-76-266

Director of Nuclear Reactor Regulation
Attention: Mr. Victor Stello, Jr., Director
Division of Operating Reactors
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Dear Mr. Stello:

TURKEY POINT UNIT 4
DOCKET NO. 50-251
INSPECTION OF SAFETY RELATED
HYDRAULIC PIPE RESTRAINTS

The subject inspection was completed on June 2, 1976 in accordance with the continuing requirements of the Directorate of Licensing letter dated November 8, 1973. The inspection showed that all but one of the safety related hydraulic pipe restraints located inside the containment were in satisfactory condition. The fluid level on a feedwater line restraint indicated below the specified value. This was caused by a slight loss of oil. However, there was sufficient oil left in the system to keep the restraint operable. The restraint was replaced by a spare unit.

Very truly yours,

Jim F. Pearson

for Robert E. Uhrig
Vice President

REU/RSA/bfp

cc: Mr. Norman C. Moseley
Jack R. Newman, Esquire

8304070172 760812
PDR ADOCK 05000250
Q PDR



COPY SENT REGION II

7444