

LICENSEE EVENT REPORT

LER 83-09/1P

CONTROL BLOCK:

							(1)
--	--	--	--	--	--	--	-----

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	V	T	V	Y	S	1	2	0	0	-	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5		
7	8	LICENSEE CODE						14	15	LICENSE NUMBER										25	26	LICENSE TYPE					30	57	CAT 58	

CON'T

0	1
7	8

REPORT SOURCE

L	6	0	5	0	0	0	2	7	1	7	0	3	2	1	8	3	8	0	3	2	2	8	3	9
60	61	DOCKET NUMBER					68	69	EVENT DATE					74	75	REPORT DATE					80			

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During the refueling outage, planned modifications of the RPS MG Set resulted in a

0 3 | PCIS isolation of the Containment Ventilation System. Slide links TAC-3 and TP-1 were

0 4 | opened on Control Room panel 9-26 to restore ventilation while allowing work on the MG

0 5 | sets to continue. This action resulted in the loss of SBTG auto-start capability from

0 6 | 0817-1023. Contrary to T.S. 3.7.C.1, irradiated fuel was moved during that time

0 7 | period in the rx. bldg. with SBTG (and therefore, secondary containment) inoperable.

0 8 | _____ 80

09		SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE						COMP. SUBCODE		VALVE SUBCODE	
7	8	S	C	A	C	Z	Z	Z	Z	Z	Z	Z	Z				
		9	10	11	12	13	18						19	20			
(17) LER/RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.							
83		83		009		01		P		0							
21		22		24		26		28		32							
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED							
H		Z		Z		Z		0000		N							
33		34		35		36		37		41							
(18)		(19)		(20)		(21)		(22)		(23)							
NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER													
N		Z		Z999													
42		43		44													
(24)		(25)		(26)													
46		47		48													

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The slide links were removed before completing the full review and approval of the

1 1 lifted lead and jumper request. When it was discovered that this action resulted in

1 2 the loss of SBGT all refueling activities were suspended until the auto-start capabili-

1 3 ty of the SBGT System was returned to service.

1 4 80

1 5 H 28 0 0 0 29 NA 30 A 31 Review of lifted lead request 32

ACTIVITY CONTENT
RELEASED OF RELEASE

1 6 Z 33 Z 34 NA

AMOUNT OF ACTIVITY (35)

LOCATION OF RELEASE (36)

NA

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	(37)	Z	(38)		NA

PERSONNEL INJURIES		NUMBER		DESCRIPTION	
1	8	0	0	0	40 NA

8 9		11 12			
TYPE		LOSS OF OR DAMAGE TO FACILITY		DESCRIPTION	
1	9	Z	(42)	<div> <div>NTA</div> <div>8304110384</div> </div>	

7	8	9	10											80	
PUBLICITY				(45)	DESCRIPTION										80
ISSUED				(44)	NA										68
2	0	N	(44)											69	
7	8	9	10											80	

NRC USE ONLY

NAME OF PREPARER J. P. Pelletier

PHONE: (802) 257-7711

8304110386 830322
PDR ADOCK 05000271
S PDR

NRC USE ONLY

3PO 917-926