

LICENSEE EVENT REPORT

LER 83-7/3L

CONTROL BLOCK: 

1	2	3	4	5	6
---	---	---	---	---	---

 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	V	T	V	Y	S	1	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4	5
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T

0	1
---	---

REPORT SOURCE 

L	6	0	5	0	0	0	2	7	1	7	-	2	2	8	8	3	8	0	3	2	5	8	3	9
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

DOCKET NUMBER 60 61 EVENT DATE 68 69 REPORT DATE 74 75

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0	2
---	---

 During surveillance testing, Reactor Bldg. Vent Rad. Monitor 17-452A actuated at

0	3
---	---

 15 mr/hr and was above T. S. Table 3.2.3 limit of 14 mr/hr. Redundant Inst. 17-452B

0	4
---	---

 tested within limits and was available. Based on the above there were no adverse

0	5
---	---

 consequences to public health and safety. There have been no previous reportable

0	6
---	---

 occurrences of this type.

0	7
---	---

0	8
---	---

0	9
---	---

SYSTEM CODE 

B	B	11
---	---	----

 CAUSE CODE 

X	12
---	----

 CAUSE SUBCODE 

Z	13
---	----

 COMPONENT CODE 

I	N	S	T	R	U	14
---	---	---	---	---	---	----

 COMP. SUBCODE 

I	15
---	----

 VALVE SUBCODE 

Z	16
---	----

LER RO REPORT NUMBER (17) 

8	3
---	---

 EVENT YEAR 

21	22
----	----

 SEQUENTIAL REPORT NO. 

0	0	7	24	26
---	---	---	----	----

 OCCURRENCE CODE 

0	3	28	29
---	---	----	----

 REPORT TYPE 

L	30
---	----

 REVISION NO. 

0	32
---	----

ACTION TAKEN 

E	18
---	----

 FUTURE ACTION 

Z	19
---	----

 EFFECT ON PLANT 

Z	20
---	----

 SHUTDOWN METHOD 

Z	21
---	----

 HOURS 

0	0	0	0	22	37	40
---	---	---	---	----	----	----

 ATTACHMENT SUBMITTED 

N	23
---	----

 NPRD-4 FORM SUB 

Y	24
---	----

 PRIME COMP. SUPPLIER 

N	25
---	----

 COMPONENT MANUFACTURER 

G	0	8	0	26	44	47
---	---	---	---	----	----	----

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1	0
---	---

 The event was due to setpoint drift. The Reactor Bldg. Vent Rad. Monitor 17-452B

1	1
---	---

 was adjusted to 12 mr/hr, tested satisfactorily and returned to service. Indicator/

1	2
---	---

 Trip Unit (17-452A) is a GE Model 112B280G12.

1	3
---	---

1	4
---	---

1	5
---	---

 FACILITY STATUS 

E	28
---	----

 % POWER 

0	8	4	29
---	---	---	----

 OTHER STATUS 

NA	44
----	----

 METHOD OF DISCOVERY 

B	31
---	----

 DISCOVERY DESCRIPTION 

Surveillance Test	32	45	46
-------------------	----	----	----

1	6
---	---

 ACTIVITY CONTENT 

Z	33
---	----

 RELEASED OF RELEASE 

Z	34
---	----

 AMOUNT OF ACTIVITY 

NA	35	44
----	----	----

 LOCATION OF RELEASE 

NA	36	45	80
----	----	----	----

1	7
---	---

 PERSONNEL EXPOSURES NUMBER 

0	0	0	37
---	---	---	----

 TYPE 

Z	38
---	----

 DESCRIPTION 

NA	39	11	12	13
----	----	----	----	----

1	8
---	---

 PERSONNEL INJURIES NUMBER 

0	0	0	40
---	---	---	----

 DESCRIPTION 

NA	41	11	12
----	----	----	----

1	9
---	---

 LOSS OF OR DAMAGE TO FACILITY TYPE 

Z	42
---	----

 DESCRIPTION 

NA	43	11	12
----	----	----	----

2	0
---	---

 PUBLICITY ISSUED 

N	44
---	----

 DESCRIPTION 

NA	45	11	12
----	----	----	----

8304110747 830325  
PDR ADOCK 05000271  
S PDR

NRC USE ONLY