

LICENSEE EVENT REPORT

CONTROL BLOCK: 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 M I D C C 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5

CON'T
REPORT SOURCE L 0 5 0 0 0 3 1 6 7 0 3 0 8 8 3 8 0 3 3 1 8 3 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10
02 DURING THE PERFORMANCE OF A SURVEILLANCE TEST ON THE SOLID STATE PROTECTION SYSTEM
03 (TRAIN B) A LOGIC TEST POSITION TESTED UNSATISFACTORILY. THIS AFFECTED THE POWER
04 RANGE HIGH FLUX RATE TRIP PORTION OF THE AUTOMATIC LOGIC, TECHNICAL SPECIFICATION
05 TABLE 3.3-1 ITEM 22. THE REQUIREMENTS OF ACTION ITEM 1 WERE MET. THE PUBLIC HEALTH
06 AND SAFETY WERE NOT AFFECTED. PREVIOUS OCCURRENCES INCLUDE: 050-315/78-067,
07 81-043 AND 050-316/78-076, 82-056.

09 I B 11 E 12 G 13 I N S T R U 14 X 15 Z 16
17 LER/RO REPORT NUMBER 8 3 21 0 3 3 24 0 3 28 L 30 0 32
ACTION TAKEN A 18 FUTURE ACTION Z 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0 0 0 0 0 0 37 ATTACHMENT SUBMITTED N 23 NFRD-4 FORM SUB. Y 24 PRIME COMP. SUPPLIER N 25 COMPONENT MANUFACTURER W 1 2 0 2 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27
10 UNIVERSAL CARD B-212 (WESTINGHOUSE, PART NO.6056D21G01) WAS FOUND TO HAVE FAILED. THE
11 LOGIC CARD WAS REPLACED, THE SURVEILLANCE TEST PROCEDURE WAS PERFORMED ON TRAIN "B"
12 TO VERIFY SYSTEM OPERABILITY. NO FURTHER ACTION IS PLANNED.

15 E 28 1 0 0 29 NA 30 B 31 SURVEILLANCE TEST 32
16 Z 33 Z 34 NA 35 NA 36
17 0 0 0 37 Z 38 NA 39
18 0 0 0 40 NA 41
19 Z 42 NA 43
20 N 44 NA 45

NAME OF PREPARER R. A. PALMER

PHONE 616/465/5901

8304110759 830331
PDR ADOCK 05000316
S PDR

NRC USE ONLY