



Carolina Power & Light Company

Brunswick Steam Electric Plant
P. O. Box 10429
Southport, NC 28461-0429

83 APR 11 AS: 48

US NRC REGION 1
ATLANTA, GEORGIA

FILE: B09-13510C
SERIAL: BSEP/83-1116

Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Region II, Suite 3100
101 Marietta Street N.W.
Atlanta, GA 30303

BRUNSWICK STEAM ELECTRIC PLANT, UNIT NO. 1
DOCKET NO. 50-325
LICENSE NO. DPR-71
SPECIAL REPORT PER TECHNICAL SPECIFICATION 3.7.8

Dear Mr. O'Reilly:

During the ongoing Unit No. 1 refueling outage, a fire barrier LCO was initiated on February 28, 1983, for a Control Building fire door. The door, No. 103, was declared inoperable due to a missing door handle. The door was repaired; however, postmaintenance testing of the door revealed it would not self-close due to encountered high differential air pressure across the door. Plant Engineering has been requested to evaluate the high differential air pressure problem. Until the return of the door to operability and cancellation of the subject LCO, appropriate stationed fire watch at this door will remain in effect.

Very truly yours,

C. R. Dietz, General Manager
Brunswick Steam Electric Plant

RMP/jo/LETJ03

Enclosure

cc: Mr. R. C. DeYoung
NRC Document Control Desk

8304130277 830411
PDR ADOCK 05000325
S PDR

OFFICIAL COPY

IE 22