

LICENSEE EVENT REPORT

Attachment to AECM-83/0176

Page 1 of 2

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 M S G G S 1 2 0 0 0 0 0 0 0 0 0 0 3 4 1 1 1 1 4 5
7 8 9 14 15 25 26 30 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

CON'T

0 1 REPORT SOURCE L 6 0 5 0 0 0 4 1 6 7 1 1 0 4 8 2 8 0 4 0 7 8 3 9
7 8 9 14 15 25 26 30 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 During a recent NRC audit of LCOs, it was discovered that an action
0 3 statement was entered per T.S.3.7.7 on July 30, 1982, and a required
0 4 Special Report pursuant to T.S.6.9.2 was not filed. This had no
0 5 effect on health and safety of the public and did not constitute a
0 6 threat to plant safety. This is an interim report submitted pursuant to
0 7 T.S.6.9.1.12.b. An update report will be submitted by May 30, 1983.
0 8
0 9

0 9 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
7 8 9 14 15 25 26 30 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

17 LER RO REPORT NUMBER 8 2 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
X 18 X 19 Z 20 Z 21 0 0 0 0 Y 23 N 24 Z 25 Z 9 9 9 9 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The action statement of T.S.3.7.7 was entered due to the incomplete
1 1 installation of fire-rated barriers on some safety related cables,
1 2 conduit, and cable trays. An hourly fire watch was established, however,
1 3 an incident report was not filed as required by plant procedures. This
1 4 resulted in the Special Report required by T.S.3.7.7 not being filed.
7 8 9 14 15 25 26 30 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

1 5 FACILITY STATUS 8 28 0 0 0 29 NA 30 31 NRC Inspection 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE
Z 33 Z 34 NA 35 NA 36

1 6 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

0 0 0 37 Z 38 NA 39

1 7 PERSONNEL INJURIES NUMBER DESCRIPTION 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

0 0 0 40 NA 41

1 8 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

Z 42 NA 43

1 9 PUBLICITY ISSUED DESCRIPTION 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

N 44 NA 45

8304130343 830407
PDR ADOCK 05000416
S PDR

NRC USE ONLY

NAME OF PREPARER Ron Byrd

PHONE

SUPPLEMENTARY INFORMATION TO
LER 82-106/01 X-1

Mississippi Power & Light Company
Grand Gulf Nuclear Station - Unit 1
Docket No. 50-416

Technical Specification Involved: 3.7.7
Reported Under Technical Specification: 6.9.1.12.b

Event Narrative:

This is an update to a previous report submitted on November 17, 1982. The following paragraphs describe the event reported.

During a recent NRC audit of LCO's, it was discovered that an action statement was entered for T.S.3.7.7 on July 30, 1982, and a required Special Report pursuant to T.S.6.9.2 was not filed.

The LCO was entered due to the incomplete installation of fire-rated barriers on some safety related cables, conduits and cable tray. An hourly fire watch was established, however, an incident report was not filed as required by plant procedures. Therefore, the Special Report required by T.S.3.7.7 was not filed.

This report was submitted pursuant to T.S.6.9.1.12.b since the Special Report required by the LCO was not filed within the time limit of T.S.3.7.7 Action (a). The plant is currently operating under the T.S.3.7.7 action statement.

During an inspection of completed work to correct the deficiencies, Field Engineering discovered similar deficiencies not previously identified by the Architect Engineer. This event was reported as LER 83-010/99 X-0.

This is submitted as an interim report. An update will be submitted by May 30, 1983.