

CONTROL BLOCK:

--	--	--	--	--	--

 ①

0	1	T	N	S	N	P	1	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5			
7	8	9	LICENSEE CODE					14	15	LICENSE NUMBER										25	26	LICENSE TYPE					30	57 CAT 56				

CON'T

0	1
---	---

REPORT SOURCE

L	6	0	5	0	0	0	3	2	7	7	0	3	1	4	8	3	8	0	4	0	8	8	3	9
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | With unit 1 in mode 1 (40% Rx power) at 1215 CST on 03/14/83, one steam flow

0 3 | channel (1-FT-1-10B) was declared inoperable due to failing high. This event

0 4 | required entry into action statement 7 of LCO 3.3.1.1. There was no effect upon

0 5 | public health and safety. Previous occurrences - none.

0 6 |

0 7 |

0 8 |

SYSTEM CODE I A (11)		CAUSE CODE X (12)		CAUSE SUBCODE Z (13)		COMPONENT CODE Z Z Z Z Z Z Z (14)						COMP. SUBCODE Z (15)		VALVE SUBCODE Z (16)			
LER/RO REPORT NUMBER 8 3 (17)		EVENT YEAR 8 3 (21-22)		SEQUENTIAL REPORT NO. 0 3 7 (24-26)		OCCURRENCE CODE 0 3 (28-29)		REPORT TYPE L (30)		REVISION NO. 0 (32)							
ACTION TAKEN X (18)		FUTURE ACTION Z (19)		EFFECT ON PLANT Z (20)		SHUTDOWN METHOD Z (21)		HOURS 0 0 0 0 (22-26)		ATTACHMENT SUBMITTED N (23)		NPRD-4 FORM SUB. N (24)		PRIME COMP. SUPPLIER Z (25)		COMPONENT MANUFACTURER Z 9 9 9 (27-30)	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | Investigation indicated that the steam flow channel failed high most probably due to

1 1 | air in the sense line. The line was backfilled and bled to remove the entrapped

1 2 | air. The loop calibration was verified and returned to service at 1200 CST on

1 3 | 03/18/83.

1 4		FACILITY STATUS		% POWER		OTHER STATUS (30)		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION (32)	
1	5	E (28)	0	4	0 (29)	NA		B (31)	Operator observation		
ACTIVITY CONTENT		RELEASED OF RELEASE		AMOUNT OF ACTIVITY (35)						LOCATION OF RELEASE (36)	
1	6	Z (33)		Z (34)	NA		NA				

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	37	Z	38	NA	

[illegible]

LOSS OF OR DAMAGE TO FACILITY (43)

TYPE	DESCRIPTION
2	NA

7 8 9 10 NA
PURLICITY 8304130373 830408 80

ISSUED DESCRIPTION (45) PDR ADDCK 05000327 NRC USE ONLY
 2 0 N (44) NA S PDR

Name of Preparer: H. R. Rogers /M. R. Harding

Phone: (615) 870-6422