

DUKE POWER COMPANY

P.O. BOX 33189
CHARLOTTE, N.C. 28242

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION

TELEPHONE
(704) 373-4531

April 1, 1983

Mr. James P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street NW, Suite 2900
Atlanta, Georgia 30303

Re: McGuire Nuclear Station Unit 1
Docket No. 50-369

03 APR 11 AS: 48

Dear Mr. O'Reilly:

Please find attached Reportable Occurrence Report RO-369/83-12. This report concerns T.S. 6.9.1.13(c), "Observed inadequacies in the implementation of administrative or procedural controls which threaten to cause reduction of degree of redundancy provided in Reactor Protection Systems or Engineered Safety Feature Systems". This incident was considered to be of no significance with respect to the health and safety of the public.

Note that this has been previously reported for Unit 2 via 10 CFR 50.55e Significant Deficiency Report SD-370/83-01.

Very truly yours,

H.B. Tucker / BT

Hal B. Tucker

PBN:jfw
Attachment

cc: Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. W. T. Orders
Senior Resident Inspector - NRC
McGuire Nuclear Station

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339

ORIGINAL COPY

TE 22

8304130396 830401
PDR ADDCK 05000369
S PDR