

UNION ELECTRIC COMPANY

1901 GRATIOT STREET
ST. LOUIS, MISSOURI

DONALD F. SCHNELL
VICE PRESIDENT

April 7, 1983

MAILING ADDRESS:
P. O. BOX 149
ST. LOUIS, MISSOURI 63166

Mr. R. L. Spessard, Director
Division of Project and Resident Programs
U. S. Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

50-483
ULNRC- 617

Dear Mr. Spessard:


INTERIM 10CFR50.55(e)/PART 21 REPORT #U-48
GE AKR-30 AND AKR-50 CIRCUIT BREAKERS

Ref: General Electric Service Advice #175/9.11

Union Electric provided Mr. J. Neisler, Callaway NRC Resident Inspector, and Mr. H. Wescott, NRC Region III, verbal notification of a deficiency reportable under 10CFR50.55(e)/Part 21 on Monday March 14, 1983. The details of this deficiency are as described in GE Distribution Equipment Division Service Advice Tab 175, No. 9.11. This deficiency had been previously reported to Mr. Neisler and Mr. Wescott as a potential significant deficiency on February 11, 1983.

As this condition is also applicable to the Wolf Creek unit, it is being handled as a generic SNUPPS deficiency. The Lead A/E has been requested to provide an assessment of the safety implications and a plan of corrective action. This plan will employ the recommendations of the reference GE advisory, as appropriate. A final report on this deficiency is expected to be submitted by April 29, 1983.

Very truly yours,



Donald F. Schnell

JJS/sla

cc: H. M. Wescott, Region III
Richard DeYoung, Director I&E
NRC Resident Inspector, Callaway Plant
Missouri Public Service Commission

8304150354 830407
PDR ADOCK 05000482
S PDR

APR 11 1983

IE29