

CONTROL BLOCK: | | | | | | | ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01	C	0	0	F	S	V	1	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	2	0	4	5					
LICENSEE CODE								LICENSE NUMBER								LICENSE TYPE								CAT 58							
CON'T																															
01	L	6	0	5	0	0	0	2	5	7	7	U	3	0	9	8	3	8	0	4	U	8	8	3	9						
REPORT SOURCE		DOCKET NUMBER								EVENT DATE								REPORT DATE													
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)																															
The ID emergency diesel of 1B emergency set tripped due to intermittent ground of the DC electrical system during Surveillance Test. This event is reportable as a degraded mode of LCO 4.6.1(d) per Fort St. Vrain Technical Specification AC 7.5.2(b)2. No accompanying occurrence. No affect on public health or safety. Redundant emergency diesel generator set was available and operable. Similar reports: R0's 82-035, 82-033, 81-066, 81-057, 81-035, 81-031, 81-029, and 81-017.																															
SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE																															
E U		X		Z		Z Z Z Z Z Z		Z		Z																					
17		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.																					
8 3		U 1 4		U 3		L		U																							
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER															
B Z		Z		Z		0 0 0 0		Y		N		N		Z 9 9 9																	
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)																															
A loose conduit termination lock nut caused an intermittent ground of the DC electrical system affecting the engine speed governor. The lock nut on the conduit was tightened and secured. Surveillance testing was satisfactorily completed. No further corrective action is anticipated or required.																															
FACILITY STATUS % POWER OTHER STATUS (30) METHOD OF DISCOVERY DISCOVERY DESCRIPTION (32)																															
E		0 2 9		N/A		B		Operator Observation																							
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)																															
Z		Z		N/A		N/A																									
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39)																															
0 0 0		Z		N/A																											
PERSONNEL INJURIES NUMBER DESCRIPTION (41)																															
U 0 0		N/A																													
LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION (43)																															
Z		N/A																													
PUBLICATION ISSUED DESCRIPTION (45)																															
N		N/A																													
NAME OF PREPARER PHONE (303) 785-2224																															

R4 IE22 •
Docket 50-267

Date
Received: 4-11-83

Date of 4-8-83
Document:

Title: INCIDENT REPORT (50 Dkt) LER/RO/AO/ETC. P-83140 + LER 83-014

Document Control Desk Rids Code H005

(Region copy, NRC PDR, LPDR, NSIC, NTIS)

LTR. ENCL.

Region IV Internal:

Region IV Supense Copy ✓

P. Wagner ✓

RRI ✓

Original sent to DMB

REGION IV ROUTING:

J. Gagliardo ✓

J. Collins

P. Check

R. Bangart

G. Madsen

Section Chief

Do not return to RIV File Room

LTR. ENCL.

Region IV External:

State: COLORADO ✓

NRR OVERSIGHT:

NRR/ORB3/BC: R.A.CLARK ✓

NRR/ORB3/PM: C.TRAMMELL ✓

NRR/DIR/DL: D.EISENHUT ✓

NRR/DIR/DE: R.VOLLMER ✓

NRR/DIR/HFS: H.THOMPSON ✓

NRR/DIR/DSI: R.MATTSON ✓

NRR/DIR/DST: S.HANAUER ✓

NRR/

Copies Required 27

Copies Received 1

Encl. only \

Letter only \

*File Copy

Other

ACRS

10 ✓

JAMES HARD ✓

IE/DEQA/EAB ✓

IE/DRP/CVSPS ✓

AEOD ✓

INPO, J.K.STARNES ✓

* One copy distributed unless otherwise indicated ()

* Original file copy will be returned to RIV