

CONTROL BLOCK: 

--	--	--	--	--	--	--

 (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

7 8 9 14 15 25 26 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58

0 1 C A S O S 2 0 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 1 1 4 5

LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT

CON'T

REPORT SOURCE: 0 1 7 0 5 0 0 0 3 6 1 7 0 3 1 5 8 3 8 0 4 1 4 8 3 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 With Units 2 and 3 in Mode 5, fire watch personnel performing routine tours found a

0 3 jammed open latch and a missing doorknob on door C3-67. By current interpretation

0 4 this door must be closed for operability of CREACUS during its actuation, so both

0 5 trains of CREACUS were declared inoperable at 1415. LCO 3.7.5, Action Statement 'b'

0 6 was satisfied because no core alterations or positive reactivity changes were

0 7 taking place. Public health and safety were not affected.

0	8	9											80				
SYSTEM CODE			CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE						COMP. SUBCODE		VALVE SUBCODE		
S	G	(11)	E	(12)	B	(13)	X	X	X	X	X	X	(14)	Z	(15)	Z	(16)
EVENT YEAR			SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.								
8	3	(17)	0	3	2	0	3	(18)	L	(19)	0	(20)					
ACTION TAKEN			FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED						
B	(18)	H	(19)	Z	(20)	Z	(21)	0	0	0	(22)	Y	(23)				
NPRD-4 FORM SUB.			PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER												
N	(24)	A	(25)	X	9	9	9	(26)									

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 5 High door usage, door modifications, and lightweight latching mechanisms contributed to the door's failure. Emergency maintenance was ordered to repair the door, and 1 1 CREACUS was declared operable at 2155 on 3/15/83. To prevent this event's 1 2 recurrence a preventive maintenance program is being developed for the doors, and 1 3 corrective maintenance will be handled as "emergency work". (See attachment.)

FACILITY STATUS: 1 5 B (28) % POWER: 0 0 0 (29) OTHER STATUS: (30) N/A METHOD OF DISCOVERY: A (31) DISCOVERY DESCRIPTION: (32) Fire Watch Tour

ACTIVITY CONTENT  
RELEASED OF RELEASE

1 6 9 Z 33 10 Z 34 11

AMOUNT OF ACTIVITY (35) N/A

LOCATION OF RELEASE (36) N/A

PERSONNEL EXPOSURES				DESCRIPTION	
NUMBER			TYPE		
1	7	00	57 Z	38	NA

PERSONNEL INJURIES		DESCRIPTION	
NUMBER			
1	0	0	0
2	0	0	0
3	0	0	0
4	0	0	0
5	0	0	0
6	0	0	0
7	0	0	0
8	0	0	0
9	0	0	0
10	0	0	0
11	0	0	0
12	0	0	0
13	0	0	0
14	0	0	0
15	0	0	0
16	0	0	0
17	0	0	0
18	0	0	0
19	0	0	0
20	0	0	0
21	0	0	0
22	0	0	0
23	0	0	0
24	0	0	0
25	0	0	0
26	0	0	0
27	0	0	0
28	0	0	0
29	0	0	0
30	0	0	0
31	0	0	0
32	0	0	0
33	0	0	0
34	0	0	0
35	0	0	0
36	0	0	0
37	0	0	0
38	0	0	0
39	0	0	0
40	0	0	0
41	0	0	0
42	0	0	0
43	0	0	0
44	0	0	0
45	0	0	0
46	0	0	0
47	0	0	0
48	0	0	0
49	0	0	0
50	0	0	0
51	0	0	0
52	0	0	0
53	0	0	0
54	0	0	0
55	0	0	0
56	0	0	0
57	0	0	0
58	0	0	0
59	0	0	0
60	0	0	0
61	0	0	0
62	0	0	0
63	0	0	0
64	0	0	0
65	0	0	0
66	0	0	0
67	0	0	0
68	0	0	0
69	0	0	0
70	0	0	0
71	0	0	0
72	0	0	0
73	0	0	0
74	0	0	0
75	0	0	0
76	0	0	0
77	0	0	0
78	0	0	0
79	0	0	0
80	0	0	0
81	0	0	0
82	0	0	0
83	0	0	0
84	0	0	0
85	0	0	0
86	0	0	0
87	0	0	0
88	0	0	0
89	0	0	0
90	0	0	0
91	0	0	0
92	0	0	0
93	0	0	0
94	0	0	0
95	0	0	0
96	0	0	0
97	0	0	0
98	0	0	0
99	0	0	0
100	0	0	0

8 9 11 12		LOSS OF OR DAMAGE TO FACILITY		(43)
TYPE		DESCRIPTION		
1	9	Z	(42)	NA

8304220581 830414  
PDR ADDCK 05000361  
S PDR

NRC USE ONLY

NA  
H. B. Ray

NAME OF PREPARER

PHONE

714/492-7700

ATTACHMENT TO LER 83-032  
SOUTHERN CALIFORNIA EDISON COMPANY  
SAN ONOFRE NUCLEAR GENERATING STATION  
UNIT NO. 2, DOCKET NO. 50-361

SUPPLEMENTAL INFORMATION FOR CAUSE DESCRIPTION  
AND CORRECTIVE ACTIONS

An hourly documented door patrol assures that the doors are functioning properly. Further actions to preclude repetition of this event will include administrative controls and compensatory measures currently under development. See also LER's 83-020 and 83-027.