

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

917-926

LER ATTACHMENT - RO #2-83-39

Facility: BSEP Unit No. 2

Event Date: March 28, 1983

As a result of an event involving this instrumentation on Unit No. 1, as reported in LER 1-81-07 and a post-TMI requirement, plant modification packages (80-79 and 80-016 for Unit No. 1 and 80-78 and 80-017 for Unit No. 2) have been developed. These modifications will install condensing pots in the reference legs of these instruments in order to increase their accuracy and reliability, and remove the requirement to have flow in their reference legs to ensure they are full.

Mr. James G. Keppler, Regional Administrator
Page Two

April 15, 1983
EF2-63499

cc: Mr. Richard DeYoung, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. Bruce Little, Senior Resident Inspector
U.S. Nuclear Regulatory Commission
6450 North Dixie Highway
Newport, Michigan 48166