



Carolina Power & Light Company

H. B. ROBINSON STEAM ELECTRIC PLANT
POST OFFICE BOX 790
HARTSVILLE, SOUTH CAROLINA 29550

APR 25 1983

Robinson File No: 13510C

Serial: RSEP/83-534

Mr. James P. O'Reilly
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT 2
DOCKET NO. 50-261
LICENSE NO. DPR-23
PROMPT NOTIFICATION - SERVICE WATER BOOSTER PUMP FAILURE


Dear Mr. O'Reilly:

In accordance with Section 6.9.2 of the Technical Specifications for the H. B. Robinson Steam Electric Plant, Unit 2, the following event is reported.

On April 24, 1983, at 0710 hours, "B" Service Water Booster Pump (SWBP) was declared inoperable due to a bearing failure. At 1407 hours, "A" SWBP tripped, and Plant shutdown was commenced in accordance with Technical Specification 3.3.4.2. The control power fuses were found blown on "A" SWBP. These fuses were replaced, and "A" SWBP was restarted. Plant shutdown was terminated at approximately 1424 hours. At 1501 hours, "A" SWBP tripped again, and Plant shutdown was recommenced. The control power fuses were replaced, and "A" SWBP was restarted; however, Plant shutdown continued pending further investigation of the failure. Hot shutdown conditions were achieved at 1759 hours.

NRC Region II and the office of Mr. B. J. Furr, Vice President - Nuclear Operations, were notified of this event on April 25, 1983.

Very truly yours,


for R. B. Starkey, Jr.
General Manager
H. B. Robinson S. E. Plant

8305030599 830425
PDR ADOCK 05000261
S PDR

HTC/jt

cc: S. P. Weise

OFFICIAL COPY

TE 22