



Commonwealth Edison

Dresden Nuclear Power Station
R.R. #1
Morris, Illinois 60450
Telephone 815/942-2920

April 25, 1983

DJS Ltr #83-405

James G. Keppler, Regional Administrator
Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Updated Reportable Occurrence Report #83-08/01X-1, Docket #050-237 is being submitted to your office in accordance with Dresden Nuclear Power Station Technical Specification 6.6.B.1.(c), abnormal degradation discovered in fuel cladding, reactor coolant pressure boundary, or primary containment. This report concerns all the rejectable indications found during the Unit 2 January, 1983 refueling outage while performing the required and augmented inservice inspection.

D. J. Scott
Station Superintendent
Dresden Nuclear Power Station

DJS/kjl

Enclosure

cc: Director of Inspection & Enforcement
Director of Management & Program Control
U.S. NRC, Document Management Branch
File/NRC

8305060511 830425
PDR ADOCK 05000237
S PDR

MAY 2 1983

IE22