

LICENSEE EVENT REPORT

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
7	8

REPORT SOURCE

L	6	0	5	0	0	0	3	6	4	7	0	4	0	4	8	3	8	0	5	0	3	8	3	9
60	61									68	69					74	75							80
DOCKET NUMBER											EVENT DATE						REPORT DATE							

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE						COMP. SUBCODE		VALUE SUBCODE										
0	9	R	B	E	G	I	N	S	T	R	U	C	Z											
7	8	9	10	11	12	13	14	15	16	17	18	19	20											
LER/RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.														
17	8	3		0	1	9	/	0	3	L	0													
21	22	23	24	25	26	27	28	29	30	31	32													
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER								
A	Z	Z						Y	0	0	0	0	Y	N	W	1	2	0						
23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

7 8 9
FACILITY STATUS 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30
% POWER 31 32 33 34 35 36 37 38 39 40 41 42 43 44
OTHER STATUS 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60
METHOD OF DISCOVERY 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80
DISCOVERY DESCRIPTION 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100
1 5 E 28 1 0 0 29 NA A 31 Operational Event 32

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	(37)	Z	(38)	NA	(39)

1 9 Z (42) NA
7 8 9 10
PUBLCITY (45) 8305100139 830503
NRC USE ONLY

ISSUED DESCRIPTION PDR ADOCK 05000364
20 N 44 S PDR
7 8 9 10 68 69 80
W. G. Hairston, III
PHONE: (250) 899-5156

Licensee Event Report
LER No. 83-019/03L-0
Page 2 of 2

CASUE DESCRIPTION AND CORRECTIVE ACTIONS (CONTINUED)

the second occurrence, phase control card B2 was replaced. The alarm was reset and following the satisfactory performance of FNP-2-STP-5.0, the rod control system was declared operable at 0842 on 4/19/83.