

DUKE POWER COMPANY

P.O. BOX 33189
CHARLOTTE, N.C. 28242

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION

May 5, 1983

TELEPHONE
(704) 373-4531

Mr. Harold R. Denton, Director
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Attention: Ms. E. G. Adensam, Chief
Licensing Branch No. 4

Re: McGuire Nuclear Station
Docket Nos. 50-369, 50-370

Dear Mr. Denton:

Our letter of May 3, 1983 identified an event which occurred on March 31, 1983 involving a problem with the McGuire Unit 1 train B reactor trip breaker. This letter is to clarify that the problem resulted in a failure of the breaker to trip upon undervoltage.

Please advise if there are additional questions.

Very truly yours,

Hal B. Tucker/hal

Hal B. Tucker

REH:jfw

cc: Mr. James P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30303

Mr. W. T. Orders
NRC Resident Inspector
McGuire Nuclear Station

B021

*Add: J. T. Beard
T. Ippolito
T. Novak
E. Adensam*

8305100327 830505
PDR ADOCK 05000369
S PDR