

W  
C  
P  
C  
C  
C

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

PHONE: 919-457-9521

LER ATTACHMENT - RO #1-83-14

Facility: Unit No. 1

Event Date: April 6, 1983

Plant modifications to install shroud-like protectors/supportive devices around the PIP connectors of control rods are scheduled for installation on Unit No. 1 during the current refuel and on Unit No. 2 during a future unit outage. It is felt these modifications will help reduce the number of control rod PIP connector failures which result from inadvertent bumping during undervessel work.