

No. 2-83-09-31

Dear Mr. Allan:

This L.E.R. deals with the failure of a smoke detector in the drywell to annunciate. Applicable Tech. Spec. 3.14.C.1.

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

[illegible]