

CONTROL BLOCK: 

--	--	--	--	--	--

 ① (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1
---	---

 N C B E P 2 ② 0 0 - 0 0 0 0 0 0 - 0 0 ③ 4 1 1 1 1 ④ ⑤

7 8 9 14 15 25 26 30 57 CAT 58

LICENSEE CODE LICENSE NUMBER LICENSE TYPE

CON'T

0	1
---	---

REPORT SOURCE

L	6	0	5	0	-	0	3	2	4	7	0	4	1	0	8	3	8	0	5	0	6	8	3	9
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

DOCKET NUMBER

EVENT DATE

REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 While replacing HFA relay coils during a unit outage it was determined that wires to

0 3 terminals 13 and 14 in the terminal box for MSIV 2-B21-F028A were reversed. Those

0 4 wires go to redundant RPS relays C72-K3A and C72-K3B. This wiring error did not affect

0 5 the RPS circuitry, however, it violated the division separation criteria. The health

0 6 and safety of the public were not affected by this event.

0 7 Technical Specification 6.9.1.9a

[illegible]

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1	0	The wires were reterminated to their proper terminals. It was not determined how the
1	1	leads were reversed. This is the only wiring problem that has been identified during
1	2	the HFA relay coil change and is considered an isolated event.
1	3	
1	4	

7 8 9 80

FACILITY STATUS (1) 5 (2) G (3) 28 (4) 0 (5) 0 (6) 0 (7) 29 (8) OTHER STATUS (9) NA (10) METHOD OF DISCOVERY (11) A (12) 31 (13) DISCOVERY DESCRIPTION (14) 32 (15) Relay Replacement (16) 80  
 ACTIVITY CONTENT (17) 1 (18) 6 (19) Z (20) 33 (21) Z (22) 34 (23) AMOUNT OF ACTIVITY (24) 35 (25) NA (26) LOCATION OF RELEASE (27) 36 (28) 80  
 PERSONNEL EXPOSURES (29) 1 (30) 7 (31) 0 (32) 0 (33) 0 (34) 37 (35) Z (36) 38 (37) DESCRIPTION (38) 39 (39) NA (40) 80  
 PERSONNEL INJURIES (41) 1 (42) 8 (43) 0 (44) 0 (45) 0 (46) 40 (47) DESCRIPTION (48) 41 (49) NA (50) 80  
 LOSS OF OR DAMAGE TO FACILITY (51) 1 (52) 9 (53) Z (54) 42 (55) DESCRIPTION (56) 43 (57) NA (58) 80  
 PUBLICITY (59) 2 (60) 0 (61) N (62) 44 (63) DESCRIPTION (64) 45 (65) 8305130176 830506 (66) PDR ADDCK 05000324 (67) S (68) PDR (69) NRC USE ONLY (70) 80

NAME OF PREPARER R. M. Poulk, Jr.

PHONE: 919-457-9521