

BOSTON EDITOR COMPANY

PROMPT REPORT OF OCCURRENCETELECOPY MESSAGETO: (215) 337-5324
Telephone Number

DATE/TIME: May 2, 1983 / 1400

TO: Regional Administrator, Region 1
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406FROM: Pilgrim Nuclear Power Station
RFD#1, Rocky Hill Road
Plymouth, MA 02360

Docket Number 50-293

License DPR-35

Assigned LER Number 83-020/01X-0

Reported per T.S. Section 6.9.B.1.f.

Event Description: Failure to perform daily surveillance testing per the requirements of Section 4.11.D of the Tech. Specs. which is required to assure compliance with Section 3.11.D of the Tech. Specs.

Cause and Corrective Action - The cause of this event is believed to be a failure

to revise PNPS Procedures when Sections 3.11.D and 4.11.D were incorporated into the PNPS Tech. Specs. (1/8/80) compounded by an inadvertent removal of these sections from the Tech. Specs. (5/10/80).

We have initiated an SRO change to PNPS Procedure 8.A.23 reflecting the requirements of Sections 3.11.D and 4.11.D. We have also initiated an investigation to determine if, since 1/8/80, we have operated in compliance with Section 3.11.D. At this time we believe that since 1/8/80, we have operated within the requirements of our power flow map and therefore have operated in compliance with Section 3.11.D.

Facility Status:

99 % Thermal MW

c) Routine Startup _____
d) Routine Shutdown _____
e) Steady State X
f) Load Changing _____

g) Shutdown _____
h) Refueling _____
i) Other _____
j) Not Applicable _____

A written followup report will be sent within two weeks.

NRC Person Notified J.R. Johnson NRC RI

Prepared by E.T. Graham

cc: Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Standard BECO. LER Distribution

8305160145 830502
PDR ADOCK 05000293
S PDR

IE22