

DUKE POWER COMPANY  
P.O. BOX 33189  
CHARLOTTE, N.C. 28242

USNRC REGION II  
ATLANTA, GEORGIA

HAL B. TUCKER  
VICE PRESIDENT  
NUCLEAR PRODUCTION

August 5, 1983

83 AUG 17 A8:06

TELEPHONE  
(704) 373-4531


Mr. James P. O'Reilly, Regional Administrator  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street NW, Suite 2900  
Atlanta, Georgia 30303

Subject: McGuire Nuclear Station Units 1 and 2  
Docket Nos. 50-369 and 50-370  
LER/RO-369/83-54 and LER/RO-370/83-33

Dear Mr. O'Reilly:

Please find attached Reportable Occurrence Reports RO-369/83-54 and RO-370/83-33. These reports concern T.S. 6.9.1.11(c), "Observed inadequacies in the implementation of administrative or procedural controls which threaten to cause reduction of degree of redundancy provided in reactor trip systems or engineered safety features systems". This incident was considered to be of no significance with respect to the health and safety of the public.

Very truly yours,



Hal B. Tucker

PBN:jfw  
Attachments

cc: Document Control Desk  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Mr. W. T. Orders  
NRC Resident Inspector  
McGuire Nuclear Station

Records Center  
Institute of Nuclear Power Operations  
1100 Circle 75 Parkway, Suite 1500  
Atlanta, Georgia 30339

8308190431 830805  
PDR ADOCK 05000369  
S PDR

OFFICIAL COPY  
IE22  
1/1