



**LOUISIANA  
POWER & LIGHT**


142 DELARONDE STREET  
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

August 12, 1983

W3I83-0283  
Q-3-A35.07.37

Mr. John T. Collins, Regional Administrator, Region IV  
U. S. Nuclear Regulatory Commission  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76012

SUBJECT: Waterford SES Unit No. 3  
Docket No. 5G-382  
Significant Construction Deficiency No. 37  
"Temperature Detectors (RTD) Failures"  
Seventh Interim Report



Reference: LP&L Letter W3I83-0194 dated May 26, 1983

Dear Mr. Collins:

The above referenced letter indicated submittal of a Final Report to the USNRC by August 12, 1983.

At the present time, the cable seals required to complete corrective action on the dual RTD sensors are scheduled to be shipped in October, 1983. A Final Report will therefore be submitted to the USNRC by December 6, 1983.

Very truly yours,

F. J. Drummond  
Manager Engineering & Technical Support

FJD/WAC/MAL/grf

cc: 1) Director  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

2) Director  
Office of Management  
Information and Program Control  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

3) Mr. E. L. Blake

4) Mr. W. M. Stevenson

8308230075 830812  
PDR ADDCK 05000382  
S PDR

IE-27  
1/0